

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ASBESTOS-ST1-10/22/08	030837677-0001	Southwest Area (sidewalk bridge level)	10/22/08	1	3.130	Asbestos	PCME	EMSL	10/23/08	< 0.00079	No	No	
ASBESTOS-ST2-10/22/08	030837677-0002	Southeast Area (sidewalk bridge level)	10/22/08	1	3.110	Asbestos	PCME	EMSL	10/23/08	< 0.00079	No	No	
ASBESTOS-ST4-10/22/08	030837677-0003	Northwest Area (street-level)	10/22/08	1	3.100	Asbestos	PCME	EMSL	10/23/08	< 0.00080	No	No	
ASBESTOS-ST5-10/22/08	030837677-0004	Firehouse #10 (roof level)	10/22/08	1	3.130	Asbestos	PCME	EMSL	10/23/08	< 0.00079	No	No	
ASBESTOS-ST10-10/22/08	030837677-0005	North Side Sidewalk Bridge	10/22/08	1	3.130	Asbestos	PCME	EMSL	10/23/08	< 0.00079	No	No	
ASBESTOS-ST11-10/22/08	030837677-0006	90 Trinity Place (roof level)	10/22/08	1	3.000	Asbestos	PCME	EMSL	10/23/08	< 0.00082	No	No	
ASBESTOS-ST12-10/22/08	030837677-0007	110 Greenwich Street (roof level)	10/22/08	1	3.060	Asbestos	PCME	EMSL	10/23/08	< 0.00081	No	No	
ASBESTOS-ST13-10/22/08	030837677-0008	Marriott Hotel, 38th Floor (roof level)	10/22/08	1	3.080	Asbestos	PCME	EMSL	10/23/08	< 0.00080	No	No	
ASBESTOS-ST14-10/22/08	030837677-0009	West Face - South end at corner (scaffolding level)	10/22/08	1	3.060	Asbestos	PCME	EMSL	10/23/08	< 0.00081	No	No	
ASBESTOS-ST15-10/22/08	030837677-0010	South Face - East end at corner (scaffolding level)	10/22/08	1	3.090	Asbestos	PCME	EMSL	10/23/08	< 0.00080	No	No	
ASBESTOS-ST16-10/22/08	030837677-0011	East Face - North end at corner (scaffolding level)	10/22/08	1	3.050	Asbestos	PCME	EMSL	10/23/08	< 0.00081	No	No	
ASBESTOS-ST17-10/22/08	030837677-0012	North Face - West end at corner (scaffolding level)	10/22/08	1	3.070	Asbestos	PCME	EMSL	10/23/08	< 0.00080	No	No	
ASBESTOS-ST1-10/23/08	030837732-0001	Southwest Area (sidewalk bridge level)	10/23/08	1	3.070	Asbestos	PCME	EMSL	10/24/08	< 0.00088	No	No	
ASBESTOS-ST2-10/23/08	030837732-0002	Southeast Area (sidewalk bridge level)	10/23/08	1	3.120	Asbestos	PCME	EMSL	10/24/08	< 0.00086	No	No	
ASBESTOS-ST5-10/23/08	030837732-0003	Firehouse #10 (roof level)	10/23/08	1	3.030	Asbestos	PCME	EMSL	10/24/08	< 0.00081	No	No	
ASBESTOS-ST10-10/23/08	030837732-0004	North Side Sidewalk Bridge	10/23/08	1	3.110	Asbestos	PCME	EMSL	10/24/08	0.00087	No	No	
ASBESTOS-ST11-10/23/08	030837732-0005	90 Trinity Place (roof level)	10/23/08	1	2.980	Asbestos	PCME	EMSL	10/24/08	< 0.00083	No	No	
ASBESTOS-ST12-10/23/08	030837732-0006	110 Greenwich Street (roof level)	10/23/08	1	3.100	Asbestos	PCME	EMSL	10/24/08	< 0.00080	No	No	
ASBESTOS-ST13-10/23/08	030837732-0007	Marriott Hotel, 38th Floor (roof level)	10/23/08	1	3.040	Asbestos	PCME	EMSL	10/24/08	< 0.00081	No	No	
ASBESTOS-ST14-10/23/08	030837732-0008	West Face - South end at corner (scaffolding level)	10/23/08	1	3.040	Asbestos	PCME	EMSL	10/24/08	< 0.00081	No	No	
ASBESTOS-ST15-10/23/08	030837732-0009	South Face - East end at corner (scaffolding level)	10/23/08	1	3.040	Asbestos	PCME	EMSL	10/24/08	< 0.00081	No	No	
ASBESTOS-ST16-10/23/08	030837732-0010	East Face - North end at corner (scaffolding level)	10/23/08	1	3.090	Asbestos	PCME	EMSL	10/24/08	< 0.00087	No	No	
ASBESTOS-ST17-10/23/08	030837732-0011	North Face - West end at corner (scaffolding level)	10/23/08	1	3.090	Asbestos	PCME	EMSL	10/24/08	< 0.00087	No	No	
ASBESTOS-ST1-10/24/08	030837887-0001	Southwest Area (sidewalk bridge level)	10/24/08	1	3.060	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST2-10/24/08	030837887-0002	Southeast Area (sidewalk bridge level)	10/24/08	1	3.060	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST5-10/24/08	030837887-0003	Firehouse #10 (roof level)	10/24/08	1	3.060	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST10-10/24/08	030837887-0004	North Side Sidewalk Bridge	10/24/08	1	3.030	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST11-10/24/08	030837887-0005	90 Trinity Place (roof level)	10/24/08	1	3.050	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST12-10/24/08	030837887-0006	110 Greenwich Street (roof level)	10/24/08	1	3.050	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST13-10/24/08	030837887-0007	Marriott Hotel, 38th Floor (roof level)	10/24/08	1	3.050	Asbestos	PCME	EMSL	10/25/08	< 0.00081	No	No	
ASBESTOS-ST14-10/24/08	030837887-0008	West Face - South end at corner (scaffolding level)	10/24/08	1	2.900	Asbestos	PCME	EMSL	10/25/08	< 0.00085	No	No	
ASBESTOS-ST15-10/24/08	030837887-0009	South Face - East end at corner (scaffolding level)	10/24/08	1	2.810	Asbestos	PCME	EMSL	10/25/08	< 0.00088	No	No	
ASBESTOS-ST16-10/24/08	030837887-0010	East Face - North end at corner (scaffolding level)	10/24/08	1	2.880	Asbestos	PCME	EMSL	10/25/08	< 0.00086	No	No	
ASBESTOS-ST17-10/24/08	030837887-0011	North Face - West end at corner (scaffolding level)	10/24/08	1	2.940	Asbestos	PCME	EMSL	10/25/08	< 0.00084	No	No	
ASBESTOS-ST1-10/25/08	030838146-0001	Southwest Area (sidewalk bridge level)	10/25/08	1	3.020	Asbestos	PCME	EMSL	10/27/08	< 0.00082	No	No	
ASBESTOS-ST2-10/25/08	030838146-0002	Southeast Area (sidewalk bridge level)	10/25/08	1	2.980	Asbestos	PCME	EMSL	10/27/08	< 0.00083	No	No	
ASBESTOS-ST5-10/25/08	030838146-0003	Firehouse #10 (roof level)	10/25/08	1	3.030	Asbestos	PCME	EMSL	10/27/08	< 0.00081	No	No	
ASBESTOS-ST10-10/25/08	030838146-0004	North Side Sidewalk Bridge	10/25/08	1	3.080	Asbestos	PCME	EMSL	10/27/08	< 0.00087	No	No	
ASBESTOS-ST11-10/25/08	030838146-0005	90 Trinity Place (roof level)	10/25/08	1	3.180	Asbestos	PCME	EMSL	10/27/08	< 0.00085	No	No	
ASBESTOS-ST12-10/25/08	030838146-0006	110 Greenwich Street (roof level)	10/25/08	1	2.920	Asbestos	PCME	EMSL	10/27/08	< 0.00085	No	No	
ASBESTOS-ST13-10/25/08	030838146-0007	Marriott Hotel, 38th Floor (roof level)	10/25/08	1	3.080	Asbestos	PCME	EMSL	10/27/08	< 0.00087	No	No	
ASBESTOS-ST14-10/25/08	030838146-0008	West Face - South end at corner (scaffolding level)	10/25/08	1	2.950	Asbestos	PCME	EMSL	10/27/08	< 0.00084	No	No	
ASBESTOS-ST15-10/25/08	030838146-0009	South Face - East end at corner (scaffolding level)	10/25/08	1	3.020	Asbestos	PCME	EMSL	10/27/08	< 0.00082	No	No	
ASBESTOS-ST16-10/25/08	030838146-0010	East Face - North end at corner (scaffolding level)	10/25/08	1	2.980	Asbestos	PCME	EMSL	10/27/08	< 0.00083	No	No	
ASBESTOS-ST17-10/25/08	030838146-0011	North Face - West end at corner (scaffolding level)	10/25/08	1	3.020	Asbestos	PCME	EMSL	10/27/08	< 0.00082	No	No	
ASBESTOS-ST1-10/26/08	030838143-0001	Southwest Area (sidewalk bridge level)	10/26/08	1	3.070	Asbestos	PCME	EMSL	10/27/08	< 0.00080	No	No	
ASBESTOS-ST2-10/26/08	030838143-0002	Southeast Area (sidewalk bridge level)	10/26/08	1	3.120	Asbestos	PCME	EMSL	10/27/08	< 0.00079	No	No	
ASBESTOS-ST4-10/26/08	030838143-0003	Northwest Area (street-level)	10/26/08	1	2.860	Asbestos	PCME	EMSL	10/27/08	< 0.00086	No	No	
ASBESTOS-ST5-10/26/08	030838143-0004	Firehouse #10 (roof level)	10/26/08	1	3.080	Asbestos	PCME	EMSL	10/27/08	< 0.00087	No	No	
ASBESTOS-ST11-10/26/08	030838143-0005	90 Trinity Place (roof level)	10/26/08	1	2.930	Asbestos	PCME	EMSL	10/27/08	< 0.00084	No	No	
ASBESTOS-ST12-10/26/08	030838143-0006	110 Greenwich Street (roof level)	10/26/08	1	3.080	Asbestos	PCME	EMSL	10/27/08	< 0.00087	No	No	
ASBESTOS-ST13-10/26/08	030838143-0007	Marriott Hotel, 38th Floor (roof level)	10/26/08	1	2.990	Asbestos	PCME	EMSL	10/27/08	< 0.00083	No	No	
ASBESTOS-ST14-10/26/08	030838143-0008	West Face - South end at corner (scaffolding level)	10/26/08	1	3.340	Asbestos	PCME	EMSL	10/27/08	< 0.00081	No	No	
ASBESTOS-ST15-10/26/08	030838143-0009	South Face - East end at corner (scaffolding level)	10/26/08	1	3.170	Asbestos	PCME	EMSL	10/27/08	< 0.00085	No	No	
ASBESTOS-ST16-10/26/08	030838143-0010	East Face - North end at corner (scaffolding level)	10/26/08	1	3.290	Asbestos	PCME	EMSL	10/27/08	< 0.00082	No	No	
ASBESTOS-ST17-10/26/08	030838143-0011	North Face - West end at corner (scaffolding level)	10/26/08	1	3.260	Asbestos	PCME	EMSL	10/27/08	< 0.00083	No	No	

Note:

1. The asbestos samples from Station 4 (Northwest Area [street level]) on October 23, 24 and 25, 2008 were not available on account of intermittent power failure.
2. The asbestos sample from Station 10 (North Side Sidewalk Bridge) on October 26, 2008 was not available for analysis on account of power failure.