

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-10/23/06	030634768-0001	Southwest Area (sidewalk bridge level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST2-10/23/06	030634768-0002	Southeast Area (sidewalk bridge level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST4-10/23/06	030634768-0003	Northwest Area (street-level)	10/23/06	1	2.970	Asbestos	PCME	EMSL	10/24/06	< 0.00083	No	No	
ASBESTOS-ST5-10/23/06	030634768-0004	Firehouse #10 (roof level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST10-10/23/06	030634768-0005	North Side Sidewalk Bridge	10/23/06	1	2.900	Asbestos	PCME	EMSL	10/24/06	< 0.00085	No	No	
ASBESTOS-ST100-10/23/06	030634768-0013	Station 10 Field Duplicate	10/23/06	1	2.800	Asbestos	PCME	EMSL	10/24/06	< 0.00088	No	No	
ASBESTOS-ST11-10/23/06	030634768-0006	90 Trinity Place (roof level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST12-10/23/06	030634768-0007	110 Greenwich Street (roof level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST13-10/23/06	030634768-0008	Marriott Hotel, 38th Floor (roof level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST14-10/23/06	030634768-0009	West Face - South end at corner (scaffolding level)	10/23/06	1	3.040	Asbestos	PCME	EMSL	10/24/06	< 0.00081	No	No	
ASBESTOS-ST15-10/23/06	030634768-0010	South Face - East end at corner (scaffolding level)	10/23/06	1	3.040	Asbestos	PCME	EMSL	10/24/06	< 0.00081	No	No	
ASBESTOS-ST16-10/23/06	030634768-0011	East Face - North end at corner (scaffolding level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST17-10/23/06	030634768-0012	North Face - West end at corner (scaffolding level)	10/23/06	1	3.020	Asbestos	PCME	EMSL	10/24/06	< 0.00082	No	No	
ASBESTOS-ST1-10/24/06	030634892-0001	Southwest Area (sidewalk bridge level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST2-10/24/06	030634892-0002	Southeast Area (sidewalk bridge level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST4-10/24/06	030634892-0003	Northwest Area (street-level)	10/24/06	1	3.120	Asbestos	PCME	EMSL	10/25/06	< 0.00079	No	No	
ASBESTOS-ST5-10/24/06	030634892-0004	Firehouse #10 (roof level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST10-10/24/06	030634892-0005	North Side Sidewalk Bridge	10/24/06	1	3.060	Asbestos	PCME	EMSL	10/25/06	< 0.00081	No	No	
ASBESTOS-ST11-10/24/06	030634892-0006	90 Trinity Place (roof level)	10/24/06	1	3.000	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST12-10/24/06	030634892-0007	110 Greenwich Street (roof level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST13-10/24/06	030634892-0008	Marriott Hotel, 38th Floor (roof level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST14-10/24/06	030634892-0009	West Face - South end at corner (scaffolding level)	10/24/06	1	3.040	Asbestos	PCME	EMSL	10/25/06	< 0.00081	No	No	
ASBESTOS-ST15-10/24/06	030634892-0010	South Face - East end at corner (scaffolding level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST16-10/24/06	030634892-0011	East Face - North end at corner (scaffolding level)	10/24/06	1	3.020	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST17-10/24/06	030634892-0012	North Face - West end at corner (scaffolding level)	10/24/06	1	3.000	Asbestos	PCME	EMSL	10/25/06	< 0.00082	No	No	
ASBESTOS-ST1-10/25/06	030635017-0001	Southwest Area (sidewalk bridge level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST2-10/25/06	030635017-0002	Southeast Area (sidewalk bridge level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST4-10/25/06	030635017-0003	Northwest Area (street-level)	10/25/06	1	3.070	Asbestos	PCME	EMSL	10/26/06	< 0.00080	No	No	
ASBESTOS-ST5-10/25/06	030635017-0004	Firehouse #10 (roof level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST10-10/25/06	030635017-0005	North Side Sidewalk Bridge	10/25/06	1	3.040	Asbestos	PCME	EMSL	10/26/06	< 0.00081	No	No	
ASBESTOS-ST11-10/25/06	030635017-0006	90 Trinity Place (roof level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST12-10/25/06	030635017-0007	110 Greenwich Street (roof level)	10/25/06	1	3.040	Asbestos	PCME	EMSL	10/26/06	< 0.00081	No	No	
ASBESTOS-ST13-10/25/06	030635017-0008	Marriott Hotel, 38th Floor (roof level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST14-10/25/06	030635017-0009	West Face - South end at corner (scaffolding level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST15-10/25/06	030635017-0010	South Face - East end at corner (scaffolding level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST16-10/25/06	030635017-0011	East Face - North end at corner (scaffolding level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	
ASBESTOS-ST17-10/25/06	030635017-0012	North Face - West end at corner (scaffolding level)	10/25/06	1	3.020	Asbestos	PCME	EMSL	10/26/06	< 0.00082	No	No	