

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-10/26/05	030532085-0001	Southwest Area (street-level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST2-10/26/05	030532085-0002	Southeast Area (sidewalk bridge level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST4-10/26/05	030532085-0003	Northwest Area (street-level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST5-10/26/05	030532085-0004	Firehouse #10 (roof level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST10-10/26/05	030532085-0005	North Side Sidewalk Bridge	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST11-10/26/05	030532085-0006	90 Trinity Place (roof level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST12-10/26/05	030532085-0007	110 Greenwich Street (roof level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST13-10/26/05	030532085-0008	Marriott Hotel, 38th Floor (roof level)	10/26/2005	1	2.970	Asbestos	PCME	EMSL	10/27/2005	< 0.00083	No	No	
ASBESTOS-ST1-10/27/05	030532209-0001	Southwest Area (street-level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	Filter from Station 11 (90 Trinity Place [roof level]) was damaged and could not be analyzed.
ASBESTOS-ST2-10/27/05	030532209-0002	Southeast Area (sidewalk bridge level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	
ASBESTOS-ST4-10/27/05	030532209-0003	Northwest Area (street-level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	
ASBESTOS-ST5-10/27/05	030532209-0004	Firehouse #10 (roof level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	
ASBESTOS-ST10-10/27/05	030532209-0005	North Side Sidewalk Bridge	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	
ASBESTOS-ST12-10/27/05	030532209-0007	110 Greenwich Street (roof level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	
ASBESTOS-ST13-10/27/05	030532209-0008	Marriott Hotel, 38th Floor (roof level)	10/27/2005	1	2.970	Asbestos	PCME	EMSL	10/28/2005	< 0.00083	No	No	