

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos PCME Concentration (f/cm3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|--------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|-------------------|------|-------------------------|-------------------------------------|-----------------------------------|--|----------|
| | | | | | | | | | | 0.0009 | | | |
| | | | | | | | | | | NA | | | |
| ASBESTOS-ST1-10/31/2007 | 030735430-0001 | Southwest Area (sidewalk bridge level) | 10/31/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00082 | No | No | |
| ASBESTOS-ST2-10/31/2007 | 030735430-0002 | Southeast Area (sidewalk bridge level) | 10/31/07 | 1 | 3.010 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00082 | No | No | |
| ASBESTOS-ST4-10/31/2007 | 030735430-0003 | Northwest Area (street-level) | 10/31/07 | 1 | 3.100 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00087 | No | No | |
| ASBESTOS-ST5-10/31/2007 | 030735430-0004 | Firehouse #10 (roof level) | 10/31/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00082 | No | No | |
| ASBESTOS-ST10-10/31/2007 | 030735430-0005 | North Side Sidewalk Bridge | 10/31/07 | 1 | 3.150 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00085 | No | No | |
| ASBESTOS-ST11-10/31/2007 | 030735430-0006 | 90 Trinity Place (roof level) | 10/31/07 | 1 | 3.050 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00081 | No | No | |
| ASBESTOS-ST12-10/31/2007 | 030735430-0007 | 110 Greenwich Street (roof level) | 10/31/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00081 | No | No | |
| ASBESTOS-ST13-10/31/2007 | 030735430-0008 | Marriott Hotel, 38th Floor (roof level) | 10/31/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00080 | No | No | |
| ASBESTOS-ST14-10/31/2007 | 030735430-0009 | West Face - South end at corner (scaffolding level) | 10/31/07 | 1 | 3.090 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00080 | No | No | |
| ASBESTOS-ST15-10/31/2007 | 030735430-0010 | South Face - East end at corner (scaffolding level) | 10/31/07 | 1 | 3.040 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00081 | No | No | |
| ASBESTOS-ST16-10/31/2007 | 030735430-0011 | East Face - North end at corner (scaffolding level) | 10/31/07 | 1 | 3.020 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00082 | No | No | |
| ASBESTOS-ST17-10/31/2007 | 030735430-0012 | North Face - West end at corner (scaffolding level) | 10/31/07 | 1 | 3.110 | Asbestos | PCME | EMSL | 11/1/07 | < 0.00087 | No | No | |