

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										<b>0.0009</b>	Air Quality Levels	Site Specific Trigger Levels	
										<b>NA</b>			
										<b>Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-11/3/08	030839199-0001	Southwest Area (sidewalk bridge level)	11/3/08	1	3.120	Asbestos	PCME	EMSL	11/4/08	< 0.00079	No	No	
ASBESTOS-ST2-11/3/08	030839199-0002	Southeast Area (sidewalk bridge level)	11/3/08	1	3.040	Asbestos	PCME	EMSL	11/4/08	< 0.00081	No	No	
ASBESTOS-ST4-11/3/08	030839199-0003	Northwest Area (street-level)	11/3/08	1	3.110	Asbestos	PCME	EMSL	11/4/08	< 0.00079	No	No	
ASBESTOS-ST5-11/3/08	030839199-0004	Firehouse #10 (roof level)	11/3/08	1	3.010	Asbestos	PCME	EMSL	11/4/08	< 0.00082	No	No	
ASBESTOS-ST10-11/3/08	030839199-0005	North Side Sidewalk Bridge	11/3/08	1	3.140	Asbestos	PCME	EMSL	11/4/08	< 0.00079	No	No	
ASBESTOS-ST11-11/3/08	030839199-0006	90 Trinity Place (roof level)	11/3/08	1	3.120	Asbestos	PCME	EMSL	11/4/08	< 0.00079	No	No	
ASBESTOS-ST12-11/3/08	030839199-0007	110 Greenwich Street (roof level)	11/3/08	1	3.090	Asbestos	PCME	EMSL	11/4/08	< 0.00080	No	No	
ASBESTOS-ST13-11/3/08	030839199-0008	Marriott Hotel, 38th Floor (roof level)	11/3/08	1	3.060	Asbestos	PCME	EMSL	11/4/08	< 0.00081	No	No	
ASBESTOS-ST14-11/3/08	030839199-0009	West Face - South end at corner (scaffolding level)	11/3/08	1	3.110	Asbestos	PCME	EMSL	11/4/08	< 0.00079	No	No	
ASBESTOS-ST15-11/3/08	030839199-0010	South Face - East end at corner (scaffolding level)	11/3/08	1	3.040	Asbestos	PCME	EMSL	11/4/08	< 0.00081	No	No	
ASBESTOS-ST16-11/3/08	030839199-0011	East Face - North end at corner (scaffolding level)	11/3/08	1	3.180	Asbestos	PCME	EMSL	11/4/08	< 0.00078	No	No	
ASBESTOS-ST17-11/3/08	030839199-0012	North Face - West end at corner (scaffolding level)	11/3/08	1	3.150	Asbestos	PCME	EMSL	11/4/08	< 0.00078	No	No	
ASBESTOS-ST1-11/4/08	030839346-0001	Southwest Area (sidewalk bridge level)	11/4/08	1	3.160	Asbestos	PCME	EMSL	11/5/08	< 0.00078	No	No	
ASBESTOS-ST2-11/4/08	030839346-0002	Southeast Area (sidewalk bridge level)	11/4/08	1	3.010	Asbestos	PCME	EMSL	11/5/08	< 0.00082	No	No	
ASBESTOS-ST4-11/4/08	030839346-0003	Northwest Area (street-level)	11/4/08	1	3.160	Asbestos	PCME	EMSL	11/5/08	< 0.00078	No	No	
ASBESTOS-ST5-11/4/08	030839346-0004	Firehouse #10 (roof level)	11/4/08	1	3.030	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST10-11/4/08	030839346-0005	North Side Sidewalk Bridge	11/4/08	1	3.090	Asbestos	PCME	EMSL	11/5/08	< 0.00080	No	No	
ASBESTOS-ST100-11/4/08	030839346-0013	Station 10 Field Duplicate	11/4/08	1	3.090	Asbestos	PCME	EMSL	11/5/08	< 0.00080	No	No	
ASBESTOS-ST11-11/4/08	030839346-0006	90 Trinity Place (roof level)	11/4/08	1	3.040	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST12-11/4/08	030839346-0007	110 Greenwich Street (roof level)	11/4/08	1	3.030	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST13-11/4/08	030839346-0008	Marriott Hotel, 38th Floor (roof level)	11/4/08	1	3.050	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST14-11/4/08	030839346-0009	West Face - South end at corner (scaffolding level)	11/4/08	1	3.050	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST15-11/4/08	030839346-0010	South Face - East end at corner (scaffolding level)	11/4/08	1	3.050	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	
ASBESTOS-ST16-11/4/08	030839346-0011	East Face - North end at corner (scaffolding level)	11/4/08	1	3.000	Asbestos	PCME	EMSL	11/5/08	< 0.00082	No	No	
ASBESTOS-ST17-11/4/08	030839346-0012	North Face - West end at corner (scaffolding level)	11/4/08	1	3.060	Asbestos	PCME	EMSL	11/5/08	< 0.00081	No	No	