

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/10/07	030736392-0001	Southwest Area (sidewalk bridge level)	11/10/07	1	2.780	Asbestos	PCME	EMSL	11/12/07	< 0.00089	No	No	
ASBESTOS-ST2-11/10/07	030736392-0002	Southeast Area (sidewalk bridge level)	11/10/07	1	2.940	Asbestos	PCME	EMSL	11/12/07	< 0.00084	No	No	
ASBESTOS-ST4-11/10/07	030736392-0003	Northwest Area (street-level)	11/10/07	1	3.010	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST5-11/10/07	030736392-0004	Firehouse #10 (roof level)	11/10/07	1	3.050	Asbestos	PCME	EMSL	11/12/07	< 0.00081	No	No	
ASBESTOS-ST10-11/10/07	030736392-0005	North Side Sidewalk Bridge	11/10/07	1	2.980	Asbestos	PCME	EMSL	11/12/07	< 0.00083	No	No	
ASBESTOS-ST11-11/10/07	030736392-0006	90 Trinity Place (roof level)	11/10/07	1	3.010	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST12-11/10/07	030736392-0007	110 Greenwich Street (roof level)	11/10/07	1	3.020	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST13-11/10/07	030736392-0008	Marriott Hotel, 38th Floor (roof level)	11/10/07	1	3.110	Asbestos	PCME	EMSL	11/12/07	< 0.00079	No	No	
ASBESTOS-ST14-11/10/07	030736392-0009	West Face - South end at corner (scaffolding level)	11/10/07	1	3.010	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST15-11/10/07	030736392-0010	South Face - East end at corner (scaffolding level)	11/10/07	1	3.150	Asbestos	PCME	EMSL	11/12/07	< 0.00078	No	No	
ASBESTOS-ST16-11/10/07	030736392-0011	East Face - North end at corner (scaffolding level)	11/10/07	1	2.970	Asbestos	PCME	EMSL	11/12/07	< 0.00083	No	No	
ASBESTOS-ST17-11/10/07	030736392-0012	North Face - West end at corner (scaffolding level)	11/10/07	1	3.020	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST1-11/11/07	030736424-0001	Southwest Area (sidewalk bridge level)	11/11/07	1	3.340	Asbestos	PCME	EMSL	11/12/07	< 0.00089	No	No	
ASBESTOS-ST2-11/11/07	030736424-0002	Southeast Area (sidewalk bridge level)	11/11/07	1	3.040	Asbestos	PCME	EMSL	11/12/07	< 0.00089	No	No	
ASBESTOS-ST4-11/11/07	030736424-0003	Northwest Area (street-level)	11/11/07	1	3.040	Asbestos	PCME	EMSL	11/12/07	< 0.00089	No	No	
ASBESTOS-ST5-11/11/07	030736424-0004	Firehouse #10 (roof level)	11/11/07	1	3.050	Asbestos	PCME	EMSL	11/12/07	< 0.00088	No	No	
ASBESTOS-ST10-11/11/07	030736424-0005	North Side Sidewalk Bridge	11/11/07	1	3.000	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST11-11/11/07	030736424-0006	90 Trinity Place (roof level)	11/11/07	1	3.040	Asbestos	PCME	EMSL	11/12/07	< 0.00089	No	No	
ASBESTOS-ST12-11/11/07	030736424-0007	110 Greenwich Street (roof level)	11/11/07	1	3.010	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST13-11/11/07	030736424-0008	Marriott Hotel, 38th Floor (roof level)	11/11/07	1	2.950	Asbestos	PCME	EMSL	11/12/07	< 0.00084	No	No	
ASBESTOS-ST14-11/11/07	030736424-0009	West Face - South end at corner (scaffolding level)	11/11/07	1	2.840	Asbestos	PCME	EMSL	11/12/07	< 0.00087	No	No	
ASBESTOS-ST15-11/11/07	030736424-0010	South Face - East end at corner (scaffolding level)	11/11/07	1	3.070	Asbestos	PCME	EMSL	11/12/07	< 0.00080	No	No	
ASBESTOS-ST16-11/11/07	030736424-0011	East Face - North end at corner (scaffolding level)	11/11/07	1	3.010	Asbestos	PCME	EMSL	11/12/07	< 0.00082	No	No	
ASBESTOS-ST17-11/11/07	030736424-0012	North Face - West end at corner (scaffolding level)	11/11/07	1	3.070	Asbestos	PCME	EMSL	11/12/07	< 0.00088	No	No	
ASBESTOS-ST1-11/12/07	030736517-0001	Southwest Area (sidewalk bridge level)	11/12/07	1	2.870	Asbestos	PCME	EMSL	11/13/07	< 0.00086	No	No	
ASBESTOS-ST2-11/12/07	030736517-0002	Southeast Area (sidewalk bridge level)	11/12/07	1	2.900	Asbestos	PCME	EMSL	11/13/07	< 0.00085	No	No	
ASBESTOS-ST4-11/12/07	030736517-0003	Northwest Area (street-level)	11/12/07	1	3.160	Asbestos	PCME	EMSL	11/13/07	< 0.00078	No	No	
ASBESTOS-ST5-11/12/07	030736517-0004	Firehouse #10 (roof level)	11/12/07	1	3.060	Asbestos	PCME	EMSL	11/13/07	< 0.00081	No	No	
ASBESTOS-ST10-11/12/07	030736517-0005	North Side Sidewalk Bridge	11/12/07	1	3.060	Asbestos	PCME	EMSL	11/13/07	< 0.00081	No	No	
ASBESTOS-ST100-11/12/07	030736517-0013	Station 10 Field Duplicate	11/12/07	1	3.140	Asbestos	PCME	EMSL	11/13/07	< 0.00079	No	No	
ASBESTOS-ST11-11/12/07	030736517-0006	90 Trinity Place (roof level)	11/12/07	1	3.060	Asbestos	PCME	EMSL	11/13/07	< 0.00081	No	No	
ASBESTOS-ST12-11/12/07	030736517-0007	110 Greenwich Street (roof level)	11/12/07	1	2.990	Asbestos	PCME	EMSL	11/13/07	< 0.00083	No	No	
ASBESTOS-ST13-11/12/07	030736517-0008	Marriott Hotel, 38th Floor (roof level)	11/12/07	1	3.000	Asbestos	PCME	EMSL	11/13/07	< 0.00082	No	No	
ASBESTOS-ST14-11/12/07	030736517-0009	West Face - South end at corner (scaffolding level)	11/12/07	1	3.090	Asbestos	PCME	EMSL	11/13/07	< 0.00080	No	No	
ASBESTOS-ST15-11/12/07	030736517-0010	South Face - East end at corner (scaffolding level)	11/12/07	1	3.070	Asbestos	PCME	EMSL	11/13/07	< 0.00080	No	No	
ASBESTOS-ST16-11/12/07	030736517-0011	East Face - North end at corner (scaffolding level)	11/12/07	1	3.000	Asbestos	PCME	EMSL	11/13/07	< 0.00082	No	No	
ASBESTOS-ST17-11/12/07	030736517-0012	North Face - West end at corner (scaffolding level)	11/12/07	1	3.090	Asbestos	PCME	EMSL	11/13/07	< 0.00080	No	No	
ASBESTOS-ST1-11/13/07	030736628-0001	Southwest Area (sidewalk bridge level)	11/13/07	1	2.980	Asbestos	PCME	EMSL	11/14/07	< 0.00083	No	No	
ASBESTOS-ST2-11/13/07	030736628-0002	Southeast Area (sidewalk bridge level)	11/13/07	1	2.840	Asbestos	PCME	EMSL	11/14/07	< 0.00087	No	No	
ASBESTOS-ST4-11/13/07	030736628-0003	Northwest Area (street-level)	11/13/07	1	3.090	Asbestos	PCME	EMSL	11/14/07	< 0.00080	No	No	
ASBESTOS-ST5-11/13/07	030736628-0004	Firehouse #10 (roof level)	11/13/07	1	3.010	Asbestos	PCME	EMSL	11/14/07	< 0.00082	No	No	
ASBESTOS-ST10-11/13/07	030736628-0005	North Side Sidewalk Bridge	11/13/07	1	2.990	Asbestos	PCME	EMSL	11/14/07	< 0.00083	No	No	
ASBESTOS-ST11-11/13/07	030736628-0006	90 Trinity Place (roof level)	11/13/07	1	2.990	Asbestos	PCME	EMSL	11/14/07	< 0.00083	No	No	
ASBESTOS-ST12-11/13/07	030736628-0007	110 Greenwich Street (roof level)	11/13/07	1	2.990	Asbestos	PCME	EMSL	11/14/07	< 0.00083	No	No	
ASBESTOS-ST13-11/13/07	030736628-0008	Marriott Hotel, 38th Floor (roof level)	11/13/07	1	3.130	Asbestos	PCME	EMSL	11/14/07	< 0.00079	No	No	
ASBESTOS-ST14-11/13/07	030736628-0009	West Face - South end at corner (scaffolding level)	11/13/07	1	3.090	Asbestos	PCME	EMSL	11/14/07	< 0.00080	No	No	
ASBESTOS-ST15-11/13/07	030736628-0010	South Face - East end at corner (scaffolding level)	11/13/07	1	3.020	Asbestos	PCME	EMSL	11/14/07	< 0.00082	No	No	
ASBESTOS-ST16-11/13/07	030736628-0011	East Face - North end at corner (scaffolding level)	11/13/07	1	3.020	Asbestos	PCME	EMSL	11/14/07	< 0.00082	No	No	
ASBESTOS-ST17-11/13/07	030736628-0012	North Face - West end at corner (scaffolding level)	11/13/07	1	3.010	Asbestos	PCME	EMSL	11/14/07	< 0.00082	No	No	
ASBESTOS-ST1-11/14/07	030736719-0001	Southwest Area (sidewalk bridge level)	11/14/07	1	2.850	Asbestos	PCME	EMSL	11/15/07	< 0.00087	No	No	
ASBESTOS-ST2-11/14/07	030736719-0002	Southeast Area (sidewalk bridge level)	11/14/07	1	3.060	Asbestos	PCME	EMSL	11/15/07	< 0.00081	No	No	
ASBESTOS-ST4-11/14/07	030736719-0003	Northwest Area (street-level)	11/14/07	1	3.340	Asbestos	PCME	EMSL	11/15/07	< 0.00074	No	No	
ASBESTOS-ST5-11/14/07	030736719-0004	Firehouse #10 (roof level)	11/14/07	1	3.040	Asbestos	PCME	EMSL	11/15/07	< 0.00081	No	No	
ASBESTOS-ST10-11/14/07	030736719-0005	North Side Sidewalk Bridge	11/14/07	1	3.120	Asbestos	PCME	EMSL	11/15/07	< 0.00079	No	No	
ASBESTOS-ST11-11/14/07	030736719-0006	90 Trinity Place (roof level)	11/14/07	1	3.020	Asbestos	PCME	EMSL	11/15/07	< 0.00082	No	No	
ASBESTOS-ST12-11/14/07	030736719-0007	110 Greenwich Street (roof level)	11/14/07	1	2.990	Asbestos	PCME	EMSL	11/15/07	< 0.00083	No	No	
ASBESTOS-ST13-11/14/07	030736719-0008	Marriott Hotel, 38th Floor (roof level)	11/14/07	1	2.920	Asbestos	PCME	EMSL	11/15/07	< 0.00085	No	No	
ASBESTOS-ST14-11/14/07	030736719-0009	West Face - South end at corner (scaffolding level)	11/14/07	1	3.060	Asbestos	PCME	EMSL	11/15/07	< 0.00081	No	No	
ASBESTOS-ST15-11/14/07	030736719-0010	South Face - East end at corner (scaffolding level)	11/14/07	1	3.140	Asbestos	PCME	EMSL	11/15/07	< 0.00079	No	No	
ASBESTOS-ST16-11/14/07	030736719-0011	East Face - North end at corner (scaffolding level)	11/14/07	1	2.930	Asbestos	PCME	EMSL	11/15/07	< 0.00084	No	No	
ASBESTOS-ST17-11/14/07	030736719-0012	North Face - West end at corner (scaffolding level)	11/14/07	1	3.010	Asbestos	PCME	EMSL	11/15/07	< 0.00082	No	No	