

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-11/12/08	030840385-0001	Southwest Area (sidewalk bridge level)	11/12/08	1	3.080	Asbestos	PCME	EMSL	11/13/08	< 0.00080	No	No	
ASBESTOS-ST2-11/12/08	030840385-0002	Southeast Area (sidewalk bridge level)	11/12/08	1	3.090	Asbestos	PCME	EMSL	11/13/08	< 0.00080	No	No	
ASBESTOS-ST4-11/12/08	030840385-0003	Northwest Area (street-level)	11/12/08	1	3.010	Asbestos	PCME	EMSL	11/13/08	< 0.00082	No	No	
ASBESTOS-ST5-11/12/08	030840385-0004	Firehouse #10 (roof level)	11/12/08	1	2.990	Asbestos	PCME	EMSL	11/13/08	< 0.00083	No	No	
ASBESTOS-ST10-11/12/08	030840385-0005	North Side Sidewalk Bridge	11/12/08	1	2.950	Asbestos	PCME	EMSL	11/13/08	< 0.00084	No	No	
ASBESTOS-ST100-11/12/08	030840385-0013	Station 10 Field Duplicate	11/12/08	1	3.110	Asbestos	PCME	EMSL	11/13/08	< 0.00079	No	No	
ASBESTOS-ST11-11/12/08	030840385-0006	90 Trinity Place (roof level)	11/12/08	1	3.050	Asbestos	PCME	EMSL	11/13/08	< 0.00081	No	No	
ASBESTOS-ST12-11/12/08	030840385-0007	110 Greenwich Street (roof level)	11/12/08	1	3.010	Asbestos	PCME	EMSL	11/13/08	< 0.00082	No	No	
ASBESTOS-ST13-11/12/08	030840385-0008	Marriott Hotel, 38th Floor (roof level)	11/12/08	1	3.020	Asbestos	PCME	EMSL	11/13/08	< 0.00082	No	No	
ASBESTOS-ST14-11/12/08	030840385-0009	West Face - South end at corner (scaffolding level)	11/12/08	1	3.080	Asbestos	PCME	EMSL	11/13/08	< 0.00080	No	No	
ASBESTOS-ST15-11/12/08	030840385-0010	South Face - East end at corner (scaffolding level)	11/12/08	1	3.080	Asbestos	PCME	EMSL	11/13/08	< 0.00080	No	No	
ASBESTOS-ST16-11/12/08	030840385-0011	East Face - North end at corner (scaffolding level)	11/12/08	1	3.010	Asbestos	PCME	EMSL	11/13/08	< 0.00082	No	No	
ASBESTOS-ST17-11/12/08	030840385-0012	North Face - West end at corner (scaffolding level)	11/12/08	1	3.040	Asbestos	PCME	EMSL	11/13/08	< 0.00081	No	No	
ASBESTOS-ST1-11/13/08	030840566-0001	Southwest Area (sidewalk bridge level)	11/13/08	1	3.160	Asbestos	PCME	EMSL	11/14/08	< 0.00078	No	No	
ASBESTOS-ST2-11/13/08	030840566-0002	Southeast Area (sidewalk bridge level)	11/13/08	1	3.030	Asbestos	PCME	EMSL	11/14/08	< 0.00081	No	No	
ASBESTOS-ST4-11/13/08	030840566-0003	Northwest Area (street-level)	11/13/08	1	3.110	Asbestos	PCME	EMSL	11/14/08	< 0.00079	No	No	
ASBESTOS-ST5-11/13/08	030840566-0004	Firehouse #10 (roof level)	11/13/08	1	2.980	Asbestos	PCME	EMSL	11/14/08	< 0.00083	No	No	
ASBESTOS-ST10-11/13/08	030840566-0005	North Side Sidewalk Bridge	11/13/08	1	2.980	Asbestos	PCME	EMSL	11/14/08	< 0.00083	No	No	
ASBESTOS-ST11-11/13/08	030840566-0006	90 Trinity Place (roof level)	11/13/08	1	3.000	Asbestos	PCME	EMSL	11/14/08	< 0.00082	No	No	
ASBESTOS-ST12-11/13/08	030840566-0007	110 Greenwich Street (roof level)	11/13/08	1	2.960	Asbestos	PCME	EMSL	11/14/08	< 0.00083	No	No	
ASBESTOS-ST13-11/13/08	030840566-0008	Marriott Hotel, 38th Floor (roof level)	11/13/08	1	3.100	Asbestos	PCME	EMSL	11/14/08	< 0.00080	No	No	
ASBESTOS-ST14-11/13/08	030840566-0009	West Face - South end at corner (scaffolding level)	11/13/08	1	3.020	Asbestos	PCME	EMSL	11/14/08	< 0.00082	No	No	
ASBESTOS-ST15-11/13/08	030840566-0010	South Face - East end at corner (scaffolding level)	11/13/08	1	3.060	Asbestos	PCME	EMSL	11/14/08	< 0.00081	No	No	
ASBESTOS-ST16-11/13/08	030840566-0011	East Face - North end at corner (scaffolding level)	11/13/08	1	3.100	Asbestos	PCME	EMSL	11/14/08	< 0.00080	No	No	
ASBESTOS-ST17-11/13/08	030840566-0012	North Face - West end at corner (scaffolding level)	11/13/08	1	3.050	Asbestos	PCME	EMSL	11/14/08	< 0.00081	No	No	
ASBESTOS-ST1-11/14/08	030840657-0001	Southwest Area (sidewalk bridge level)	11/14/08	1	2.880	Asbestos	PCME	EMSL	11/15/08	< 0.00086	No	No	
ASBESTOS-ST2-11/14/08	030840657-0002	Southeast Area (sidewalk bridge level)	11/14/08	1	3.100	Asbestos	PCME	EMSL	11/15/08	< 0.00080	No	No	
ASBESTOS-ST4-11/14/08	030840657-0003	Northwest Area (street-level)	11/14/08	1	3.020	Asbestos	PCME	EMSL	11/15/08	< 0.00082	No	No	
ASBESTOS-ST5-11/14/08	030840657-0004	Firehouse #10 (roof level)	11/14/08	1	3.030	Asbestos	PCME	EMSL	11/15/08	< 0.00081	No	No	
ASBESTOS-ST10-11/14/08	030840657-0005	North Side Sidewalk Bridge	11/14/08	1	3.120	Asbestos	PCME	EMSL	11/15/08	< 0.00079	No	No	
ASBESTOS-ST11-11/14/08	030840657-0006	90 Trinity Place (roof level)	11/14/08	1	3.050	Asbestos	PCME	EMSL	11/15/08	< 0.00081	No	No	
ASBESTOS-ST12-11/14/08	030840657-0007	110 Greenwich Street (roof level)	11/14/08	1	3.040	Asbestos	PCME	EMSL	11/15/08	< 0.00081	No	No	
ASBESTOS-ST13-11/14/08	030840657-0008	Marriott Hotel, 38th Floor (roof level)	11/14/08	1	3.170	Asbestos	PCME	EMSL	11/15/08	< 0.00078	No	No	
ASBESTOS-ST14-11/14/08	030840657-0009	West Face - South end at corner (scaffolding level)	11/14/08	1	2.900	Asbestos	PCME	EMSL	11/15/08	< 0.00085	No	No	
ASBESTOS-ST15-11/14/08	030840657-0010	South Face - East end at corner (scaffolding level)	11/14/08	1	2.900	Asbestos	PCME	EMSL	11/15/08	< 0.00085	No	No	
ASBESTOS-ST16-11/14/08	030840657-0011	East Face - North end at corner (scaffolding level)	11/14/08	1	2.910	Asbestos	PCME	EMSL	11/15/08	< 0.00085	No	No	
ASBESTOS-ST17-11/14/08	030840657-0012	North Face - West end at corner (scaffolding level)	11/14/08	1	2.860	Asbestos	PCME	EMSL	11/15/08	< 0.00086	No	No	