

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-11/15/05	030534469-0001	Southwest Area (street-level)	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST2-11/15/05	030534469-0002	Southeast Area (sidewalk bridge level)	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST4-11/15/05	030534469-0003	Northwest Area (street-level)	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST5-11/15/05	030534469-0004	Firehouse #10 (roof level)	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST10-11/15/05	030534469-0005	North Side Sidewalk Bridge	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST11-11/15/05	030534469-0006	90 Trinity Place (roof level)	11/15/05	1	2.970	Asbestos	PCME	EMSL	11/16/05	< 0.00083	No	No	
ASBESTOS-ST12-11/15/05	030534469-0007	110 Greenwich Street (roof level)	11/15/05	1	3.020	Asbestos	PCME	EMSL	11/16/05	< 0.00082	No	No	
ASBESTOS-ST13-11/15/05	030534469-0008	Marriott Hotel, 38th Floor (roof level)	11/15/05	1	3.020	Asbestos	PCME	EMSL	11/16/05	< 0.00082	No	No	
ASBESTOS-ST1-11/16/05	030534645-0001	Southwest Area (street-level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST2-11/16/05	030534645-0002	Southeast Area (sidewalk bridge level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST4-11/16/05	030534645-0003	Northwest Area (street-level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST5-11/16/05	030534645-0004	Firehouse #10 (roof level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST10-11/16/05	030534645-0005	North Side Sidewalk Bridge	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST11-11/16/05	030534645-0006	90 Trinity Place (roof level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST12-11/16/05	030534645-0007	110 Greenwich Street (roof level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST13-11/16/05	030534645-0008	Marriott Hotel, 38th Floor (roof level)	11/16/05	1	2.970	Asbestos	PCME	EMSL	11/17/05	< 0.00083	No	No	
ASBESTOS-ST1-11/17/05	030534767-0001	Southwest Area (street-level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST2-11/17/05	030534767-0002	Southeast Area (sidewalk bridge level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST4-11/17/05	030534767-0003	Northwest Area (street-level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST5-11/17/05	030534767-0004	Firehouse #10 (roof level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST10-11/17/05	030534767-0005	North Side Sidewalk Bridge	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST11-11/17/05	030534767-0006	90 Trinity Place (roof level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST12-11/17/05	030534767-0007	110 Greenwich Street (roof level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST13-11/17/05	030534767-0008	Marriott Hotel, 38th Floor (roof level)	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	
ASBESTOS-ST100-11/17/05	030534767-0009	Station 10 Field Duplicate	11/17/05	1	2.970	Asbestos	PCME	EMSL	11/19/05	< 0.00083	No	No	