

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-11/23/07	030737397-0001	Southwest Area (sidewalk bridge level)	11/23/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST2-11/23/07	030737397-0002	Southeast Area (sidewalk bridge level)	11/23/07	1	3.140	Asbestos	PCME	EMSL	11/26/07	< 0.00079	No	No	
ASBESTOS-ST4-11/23/07	030737397-0003	Northwest Area (street-level)	11/23/07	1	3.040	Asbestos	PCME	EMSL	11/26/07	< 0.00081	No	No	
ASBESTOS-ST5-11/23/07	030737397-0004	Firehouse #10 (roof level)	11/23/07	1	2.990	Asbestos	PCME	EMSL	11/26/07	< 0.00083	No	No	
ASBESTOS-ST10-11/23/07	030737397-0005	North Side Sidewalk Bridge	11/23/07	1	2.920	Asbestos	PCME	EMSL	11/26/07	< 0.00085	No	No	
ASBESTOS-ST11-11/23/07	030737397-0006	90 Trinity Place (roof level)	11/23/07	1	3.020	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST12-11/23/07	030737397-0007	110 Greenwich Street (roof level)	11/23/07	1	3.040	Asbestos	PCME	EMSL	11/26/07	< 0.00081	No	No	
ASBESTOS-ST13-11/23/07	030737397-0008	Marriott Hotel, 38th Floor (roof level)	11/23/07	1	2.940	Asbestos	PCME	EMSL	11/26/07	< 0.00084	No	No	
ASBESTOS-ST14-11/23/07	030737397-0009	West Face - South end at corner (scaffolding level)	11/23/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST15-11/23/07	030737397-0010	South Face - East end at corner (scaffolding level)	11/23/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST16-11/23/07	030737397-0011	East Face - North end at corner (scaffolding level)	11/23/07	1	3.140	Asbestos	PCME	EMSL	11/26/07	< 0.00079	No	No	
ASBESTOS-ST17-11/23/07	030737397-0012	North Face - West end at corner (scaffolding level)	11/23/07	1	3.000	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST1-11/24/07	030737392-0001	Southwest Area (sidewalk bridge level)	11/24/07	1	2.990	Asbestos	PCME	EMSL	11/26/07	< 0.00083	No	No	
ASBESTOS-ST2-11/24/07	030737392-0002	Southeast Area (sidewalk bridge level)	11/24/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST4-11/24/07	030737392-0003	Northwest Area (street-level)	11/24/07	1	2.910	Asbestos	PCME	EMSL	11/26/07	< 0.00085	No	No	
ASBESTOS-ST5-11/24/07	030737392-0004	Firehouse #10 (roof level)	11/24/07	1	3.020	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST10-11/24/07	030737392-0005	North Side Sidewalk Bridge	11/24/07	1	2.990	Asbestos	PCME	EMSL	11/26/07	< 0.00083	No	No	
ASBESTOS-ST11-11/24/07	030737392-0006	90 Trinity Place (roof level)	11/24/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST12-11/24/07	030737392-0007	110 Greenwich Street (roof level)	11/24/07	1	3.020	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST13-11/24/07	030737392-0008	Marriott Hotel, 38th Floor (roof level)	11/24/07	1	3.040	Asbestos	PCME	EMSL	11/26/07	< 0.00081	No	No	
ASBESTOS-ST14-11/24/07	030737392-0009	West Face - South end at corner (scaffolding level)	11/24/07	1	3.020	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST15-11/24/07	030737392-0010	South Face - East end at corner (scaffolding level)	11/24/07	1	2.970	Asbestos	PCME	EMSL	11/26/07	< 0.00083	No	No	
ASBESTOS-ST16-11/24/07	030737392-0011	East Face - North end at corner (scaffolding level)	11/24/07	1	2.930	Asbestos	PCME	EMSL	11/26/07	< 0.00084	No	No	
ASBESTOS-ST17-11/24/07	030737392-0012	North Face - West end at corner (scaffolding level)	11/24/07	1	3.030	Asbestos	PCME	EMSL	11/26/07	< 0.00081	No	No	
ASBESTOS-ST1-11/25/07	030737394-0001	Southwest Area (sidewalk bridge level)	11/25/07	1	2.940	Asbestos	PCME	EMSL	11/26/07	< 0.00084	No	No	
ASBESTOS-ST2-11/25/07	030737394-0002	Southeast Area (sidewalk bridge level)	11/25/07	1	3.280	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST4-11/25/07	030737394-0003	Northwest Area (street-level)	11/25/07	1	3.000	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST5-11/25/07	030737394-0004	Firehouse #10 (roof level)	11/25/07	1	2.990	Asbestos	PCME	EMSL	11/26/07	< 0.00083	No	No	
ASBESTOS-ST10-11/25/07	030737394-0005	North Side Sidewalk Bridge	11/25/07	1	3.140	Asbestos	PCME	EMSL	11/26/07	< 0.00086	No	No	
ASBESTOS-ST11-11/25/07	030737394-0006	90 Trinity Place (roof level)	11/25/07	1	3.000	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST12-11/25/07	030737394-0007	110 Greenwich Street (roof level)	11/25/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST13-11/25/07	030737394-0008	Marriott Hotel, 38th Floor (roof level)	11/25/07	1	3.060	Asbestos	PCME	EMSL	11/26/07	< 0.00081	No	No	
ASBESTOS-ST14-11/25/07	030737394-0009	West Face - South end at corner (scaffolding level)	11/25/07	1	3.020	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST15-11/25/07	030737394-0010	South Face - East end at corner (scaffolding level)	11/25/07	1	2.940	Asbestos	PCME	EMSL	11/26/07	< 0.00084	No	No	
ASBESTOS-ST16-11/25/07	030737394-0011	East Face - North end at corner (scaffolding level)	11/25/07	1	3.010	Asbestos	PCME	EMSL	11/26/07	< 0.00082	No	No	
ASBESTOS-ST17-11/25/07	030737394-0012	North Face - West end at corner (scaffolding level)	11/25/07	1	2.770	Asbestos	PCME	EMSL	11/26/07	< 0.00089	No	No	