

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>										<b>0.0009</b>			
<b>EPA Site Specific Trigger Levels</b>										<b>NA</b>			
ASBESTOS-ST1-11/30/05	030535971-0001	Southwest Area (sidewalk bridge level)	11/30/05	1	3.010	Asbestos	PCME	EMSL	12/1/05	< 0.00082	No	No	
ASBESTOS-ST2-11/30/05	030535971-0002	Southeast Area (sidewalk bridge level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST4-11/30/05	030535971-0003	Northwest Area (street-level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST5-11/30/05	030535971-0004	Firehouse #10 (roof level)	11/30/05	1	3.000	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST10-11/30/05	030535971-0005	North Side Sidewalk Bridge	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST11-11/30/05	030535971-0006	90 Trinity Place (roof level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST12-11/30/05	030535971-0007	110 Greenwich Street (roof level)	11/30/05	1	2.940	Asbestos	PCME	EMSL	12/1/05	< 0.00084	No	No	
ASBESTOS-ST13-11/30/05	030535971-0008	Marriott Hotel, 38th Floor (roof level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST14-11/30/05	030535971-0009	West Face - South end at corner (scaffolding level)	11/30/05	1	2.130	Asbestos	PCME	EMSL	12/1/05	< 0.00087	No	No	
ASBESTOS-ST15-11/30/05	030535971-0010	South Face - East end at corner (scaffolding level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST16-11/30/05	030535971-0011	East Face - North end at corner (scaffolding level)	11/30/05	1	2.970	Asbestos	PCME	EMSL	12/1/05	< 0.00083	No	No	
ASBESTOS-ST17-11/30/05	030535971-0012	North Face - West end at corner (scaffolding level)	11/30/05	1	3.020	Asbestos	PCME	EMSL	12/1/05	< 0.00082	No	No	
ASBESTOS-ST1-12/1/05	030536064-0001	Southwest Area (sidewalk bridge level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST2-12/1/05	030536064-0002	Southeast Area (sidewalk bridge level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST4-12/1/05	030536064-0003	Northwest Area (street-level)	12/1/05	1	3.080	Asbestos	PCME	EMSL	12/2/05	< 0.00080	No	No	
ASBESTOS-ST5-12/1/05	030536064-0004	Firehouse #10 (roof level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST10-12/1/05	030536064-0005	North Side Sidewalk Bridge	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST11-12/1/05	030536064-0006	90 Trinity Place (roof level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST12-12/1/05	030536064-0007	110 Greenwich Street (roof level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST13-12/1/05	030536064-0008	Marriott Hotel, 38th Floor (roof level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST14-12/1/05	030536064-0009	West Face - South end at corner (scaffolding level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST15-12/1/05	030536064-0010	South Face - East end at corner (scaffolding level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST16-12/1/05	030536064-0011	East Face - North end at corner (scaffolding level)	12/1/05	1	2.970	Asbestos	PCME	EMSL	12/2/05	< 0.00083	No	No	
ASBESTOS-ST17-12/1/05	030536064-0012	North Face - West end at corner (scaffolding level)	12/1/05	1	2.940	Asbestos	PCME	EMSL	12/2/05	< 0.00084	No	No	