

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-12/2/08	030842486-0001	Southwest Area (sidewalk bridge level)	12/2/08	1	3.060	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST2-12/2/08	030842486-0002	Southeast Area (sidewalk bridge level)	12/2/08	1	3.010	Asbestos	PCME	EMSL	12/3/08	< 0.00082	No	No	
ASBESTOS-ST4-12/2/08	030842486-0003	Northwest Area (street-level)	12/2/08	1	3.100	Asbestos	PCME	EMSL	12/3/08	< 0.00080	No	No	
ASBESTOS-ST5-12/2/08	030842486-0004	Firehouse #10 (roof level)	12/2/08	1	3.050	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST10-12/2/08	030842486-0005	North Side Sidewalk Bridge	12/2/08	1	3.000	Asbestos	PCME	EMSL	12/3/08	< 0.00082	No	No	
ASBESTOS-ST11-12/2/08	030842486-0006	90 Trinity Place (roof level)	12/2/08	1	3.030	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST12-12/2/08	030842486-0007	110 Greenwich Street (roof level)	12/2/08	1	3.060	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST13-12/2/08	030842486-0008	Marriott Hotel, 38th Floor (roof level)	12/2/08	1	3.040	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST14-12/2/08	030842486-0009	West Face - South end at corner (scaffolding level)	12/2/08	1	3.070	Asbestos	PCME	EMSL	12/3/08	< 0.00080	No	No	
ASBESTOS-ST15-12/2/08	030842486-0010	South Face - East end at corner (scaffolding level)	12/2/08	1	2.970	Asbestos	PCME	EMSL	12/3/08	< 0.00083	No	No	
ASBESTOS-ST16-12/2/08	030842486-0011	East Face - North end at corner (scaffolding level)	12/2/08	1	3.040	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST17-12/2/08	030842486-0012	North Face - West end at corner (scaffolding level)	12/2/08	1	3.030	Asbestos	PCME	EMSL	12/3/08	< 0.00081	No	No	
ASBESTOS-ST1-12/3/08	030842618-0001	Southwest Area (sidewalk bridge level)	12/3/08	1	3.090	Asbestos	PCME	EMSL	12/4/08	< 0.00080	No	No	
ASBESTOS-ST2-12/3/08	030842618-0002	Southeast Area (sidewalk bridge level)	12/3/08	1	3.040	Asbestos	PCME	EMSL	12/4/08	< 0.00081	No	No	
ASBESTOS-ST4-12/3/08	030842618-0003	Northwest Area (street-level)	12/3/08	1	3.120	Asbestos	PCME	EMSL	12/4/08	< 0.00079	No	No	
ASBESTOS-ST5-12/3/08	030842618-0004	Firehouse #10 (roof level)	12/3/08	1	3.000	Asbestos	PCME	EMSL	12/4/08	< 0.00082	No	No	
ASBESTOS-ST10-12/3/08	030842618-0005	North Side Sidewalk Bridge	12/3/08	1	3.020	Asbestos	PCME	EMSL	12/4/08	< 0.00082	No	No	
ASBESTOS-ST11-12/3/08	030842618-0006	90 Trinity Place (roof level)	12/3/08	1	3.000	Asbestos	PCME	EMSL	12/4/08	< 0.00082	No	No	
ASBESTOS-ST12-12/3/08	030842618-0007	110 Greenwich Street (roof level)	12/3/08	1	2.840	Asbestos	PCME	EMSL	12/4/08	< 0.00087	No	No	
ASBESTOS-ST13-12/3/08	030842618-0008	Marriott Hotel, 38th Floor (roof level)	12/3/08	1	3.020	Asbestos	PCME	EMSL	12/4/08	< 0.00082	No	No	
ASBESTOS-ST14-12/3/08	030842618-0009	West Face - South end at corner (scaffolding level)	12/3/08	1	3.120	Asbestos	PCME	EMSL	12/4/08	< 0.00079	No	No	
ASBESTOS-ST15-12/3/08	030842618-0010	South Face - East end at corner (scaffolding level)	12/3/08	1	3.030	Asbestos	PCME	EMSL	12/4/08	< 0.00081	No	No	
ASBESTOS-ST16-12/3/08	030842618-0011	East Face - North end at corner (scaffolding level)	12/3/08	1	3.030	Asbestos	PCME	EMSL	12/4/08	< 0.00081	No	No	
ASBESTOS-ST17-12/3/08	030842618-0012	North Face - West end at corner (scaffolding level)	12/3/08	1	2.950	Asbestos	PCME	EMSL	12/4/08	< 0.00084	No	No	
ASBESTOS-ST1-12/4/08	030842713-0001	Southwest Area (sidewalk bridge level)	12/4/08	1	3.120	Asbestos	PCME	EMSL	12/5/08	< 0.00086	No	No	
ASBESTOS-ST2-12/4/08	030842713-0002	Southeast Area (sidewalk bridge level)	12/4/08	1	3.090	Asbestos	PCME	EMSL	12/5/08	< 0.00087	No	No	
ASBESTOS-ST4-12/4/08	030842713-0003	Northwest Area (street-level)	12/4/08	1	3.100	Asbestos	PCME	EMSL	12/5/08	< 0.00087	No	No	
ASBESTOS-ST5-12/4/08	030842713-0004	Firehouse #10 (roof level)	12/4/08	1	3.010	Asbestos	PCME	EMSL	12/5/08	< 0.00082	No	No	
ASBESTOS-ST10-12/4/08	030842713-0005	North Side Sidewalk Bridge	12/4/08	1	3.010	Asbestos	PCME	EMSL	12/5/08	< 0.00082	No	No	
ASBESTOS-ST11-12/4/08	030842713-0006	90 Trinity Place (roof level)	12/4/08	1	3.040	Asbestos	PCME	EMSL	12/5/08	< 0.00081	No	No	
ASBESTOS-ST12-12/4/08	030842713-0007	110 Greenwich Street (roof level)	12/4/08	1	3.100	Asbestos	PCME	EMSL	12/5/08	< 0.00087	No	No	
ASBESTOS-ST13-12/4/08	030842713-0008	Marriott Hotel, 38th Floor (roof level)	12/4/08	1	3.040	Asbestos	PCME	EMSL	12/5/08	< 0.00081	No	No	
ASBESTOS-ST14-12/4/08	030842713-0009	West Face - South end at corner (scaffolding level)	12/4/08	1	3.020	Asbestos	PCME	EMSL	12/5/08	< 0.00082	No	No	
ASBESTOS-ST15-12/4/08	030842713-0010	South Face - East end at corner (scaffolding level)	12/4/08	1	3.050	Asbestos	PCME	EMSL	12/5/08	< 0.00081	No	No	
ASBESTOS-ST16-12/4/08	030842713-0011	East Face - North end at corner (scaffolding level)	12/4/08	1	3.040	Asbestos	PCME	EMSL	12/5/08	< 0.00081	No	No	
ASBESTOS-ST17-12/4/08	030842713-0012	North Face - West end at corner (scaffolding level)	12/4/08	1	3.060	Asbestos	PCME	EMSL	12/5/08	< 0.00081	No	No	