

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-12/05/06	030639389-0001	Southwest Area (sidewalk bridge level)	12/5/06	1	3.080	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST2-12/05/06	030639389-0002	Southeast Area (sidewalk bridge level)	12/5/06	1	3.080	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST4-12/05/06	030639389-0003	Northwest Area (street-level)	12/5/06	1	3.210	Asbestos	PCME	EMSL	12/6/06	< 0.00077	No	No	
ASBESTOS-ST5-12/05/06	030639389-0004	Firehouse #10 (roof level)	12/5/06	1	3.100	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST10-12/05/06	030639389-0005	North Side Sidewalk Bridge	12/5/06	1	3.080	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST11-12/05/06	030639389-0006	90 Trinity Place (roof level)	12/5/06	1	3.100	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST12-12/05/06	030639389-0007	110 Greenwich Street (roof level)	12/5/06	1	3.100	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST13-12/05/06	030639389-0008	Marriott Hotel, 38th Floor (roof level)	12/5/06	1	3.130	Asbestos	PCME	EMSL	12/6/06	< 0.00079	No	No	
ASBESTOS-ST14-12/05/06	030639389-0009	West Face - South end at corner (scaffolding level)	12/5/06	1	3.100	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST15-12/05/06	030639389-0010	South Face - East end at corner (scaffolding level)	12/5/06	1	3.100	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST16-12/05/06	030639389-0011	East Face - North end at corner (scaffolding level)	12/5/06	1	3.090	Asbestos	PCME	EMSL	12/6/06	< 0.00080	No	No	
ASBESTOS-ST17-12/05/06	030639389-0012	North Face - West end at corner (scaffolding level)	12/5/06	1	3.120	Asbestos	PCME	EMSL	12/6/06	< 0.00079	No	No	
ASBESTOS-ST1-12/06/06	030639502-0001	Southwest Area (sidewalk bridge level)	12/6/06	1	3.100	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST2-12/06/06	030639502-0002	Southeast Area (sidewalk bridge level)	12/6/06	1	3.130	Asbestos	PCME	EMSL	12/7/06	< 0.00079	No	No	
ASBESTOS-ST4-12/06/06	030639502-0003	Northwest Area (street-level)	12/6/06	1	3.190	Asbestos	PCME	EMSL	12/7/06	< 0.00077	No	No	
ASBESTOS-ST5-12/06/06	030639502-0004	Firehouse #10 (roof level)	12/6/06	1	3.100	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST10-12/06/06	030639502-0005	North Side Sidewalk Bridge	12/6/06	1	3.310	Asbestos	PCME	EMSL	12/7/06	< 0.00075	No	No	
ASBESTOS-ST11-12/06/06	030639502-0006	90 Trinity Place (roof level)	12/6/06	1	3.090	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST12-12/06/06	030639502-0007	110 Greenwich Street (roof level)	12/6/06	1	3.090	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST13-12/06/06	030639502-0008	Marriott Hotel, 38th Floor (roof level)	12/6/06	1	3.120	Asbestos	PCME	EMSL	12/7/06	< 0.00079	No	No	
ASBESTOS-ST14-12/06/06	030639502-0009	West Face - South end at corner (scaffolding level)	12/6/06	1	3.100	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST15-12/06/06	030639502-0010	South Face - East end at corner (scaffolding level)	12/6/06	1	3.100	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST16-12/06/06	030639502-0011	East Face - North end at corner (scaffolding level)	12/6/06	1	3.100	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST17-12/06/06	030639502-0012	North Face - West end at corner (scaffolding level)	12/6/06	1	3.080	Asbestos	PCME	EMSL	12/7/06	< 0.00080	No	No	
ASBESTOS-ST1-12/7/06	030639606-0001	Southwest Area (sidewalk bridge level)	12/7/06	1	3.040	Asbestos	PCME	EMSL	12/8/06	< 0.00081	No	No	
ASBESTOS-ST2-12/7/06	030639606-0002	Southeast Area (sidewalk bridge level)	12/7/06	1	3.130	Asbestos	PCME	EMSL	12/8/06	< 0.00079	No	No	
ASBESTOS-ST4-12/7/06	030639606-0003	Northwest Area (street-level)	12/7/06	1	3.300	Asbestos	PCME	EMSL	12/8/06	< 0.00082	No	No	
ASBESTOS-ST5-12/7/06	030639606-0004	Firehouse #10 (roof level)	12/7/06	1	3.090	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	
ASBESTOS-ST10-12/7/06	030639606-0005	North Side Sidewalk Bridge	12/7/06	1	3.300	Asbestos	PCME	EMSL	12/8/06	< 0.00082	No	No	
ASBESTOS-ST11-12/7/06	030639606-0006	90 Trinity Place (roof level)	12/7/06	1	3.150	Asbestos	PCME	EMSL	12/8/06	< 0.00078	No	No	
ASBESTOS-ST12-12/7/06	030639606-0007	110 Greenwich Street (roof level)	12/7/06	1	3.100	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	
ASBESTOS-ST13-12/7/06	030639606-0008	Marriott Hotel, 38th Floor (roof level)	12/7/06	1	2.900	Asbestos	PCME	EMSL	12/8/06	< 0.00085	No	No	
ASBESTOS-ST14-12/7/06	030639606-0009	West Face - South end at corner (scaffolding level)	12/7/06	1	3.100	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	
ASBESTOS-ST15-12/7/06	030639606-0010	South Face - East end at corner (scaffolding level)	12/7/06	1	3.100	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	
ASBESTOS-ST16-12/7/06	030639606-0011	East Face - North end at corner (scaffolding level)	12/7/06	1	3.100	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	
ASBESTOS-ST17-12/7/06	030639606-0012	North Face - West end at corner (scaffolding level)	12/7/06	1	3.100	Asbestos	PCME	EMSL	12/8/06	< 0.00080	No	No	