

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-12/7/07	030738433-0001	Southwest Area (sidewalk bridge level)	12/7/07	1	3.200	Asbestos	PCME	EMSL	12/8/07	< 0.00084	No	No	
ASBESTOS-ST2-12/7/07	030738433-0002	Southeast Area (sidewalk bridge level)	12/7/07	1	3.180	Asbestos	PCME	EMSL	12/8/07	< 0.00085	No	No	
ASBESTOS-ST4-12/7/07	030738433-0003	Northwest Area (street-level)	12/7/07	1	3.260	Asbestos	PCME	EMSL	12/8/07	< 0.00083	No	No	
ASBESTOS-ST5-12/7/07	030738433-0004	Firehouse #10 (roof level)	12/7/07	1	3.040	Asbestos	PCME	EMSL	12/8/07	< 0.00081	No	No	
ASBESTOS-ST10-12/7/07	030738433-0005	North Side Sidewalk Bridge	12/7/07	1	3.250	Asbestos	PCME	EMSL	12/8/07	< 0.00083	No	No	
ASBESTOS-ST11-12/7/07	030738433-0006	90 Trinity Place (roof level)	12/7/07	1	3.050	Asbestos	PCME	EMSL	12/8/07	< 0.00088	No	No	
ASBESTOS-ST12-12/7/07	030738433-0007	110 Greenwich Street (roof level)	12/7/07	1	2.960	Asbestos	PCME	EMSL	12/8/07	< 0.00083	No	No	
ASBESTOS-ST13-12/7/07	030738433-0008	Marriott Hotel, 38th Floor (roof level)	12/7/07	1	3.010	Asbestos	PCME	EMSL	12/8/07	< 0.00082	No	No	
ASBESTOS-ST14-12/7/07	030738433-0009	West Face - South end at corner (scaffolding level)	12/7/07	1	3.040	Asbestos	PCME	EMSL	12/8/07	< 0.00075	No	No	
ASBESTOS-ST15-12/7/07	030738433-0010	South Face - East end at corner (scaffolding level)	12/7/07	1	2.970	Asbestos	PCME	EMSL	12/8/07	< 0.00071	No	No	
ASBESTOS-ST16-12/7/07	030738433-0011	East Face - North end at corner (scaffolding level)	12/7/07	1	3.050	Asbestos	PCME	EMSL	12/8/07	< 0.00075	No	No	
ASBESTOS-ST17-12/7/07	030738433-0012	North Face - West end at corner (scaffolding level)	12/7/07	1	3.010	Asbestos	PCME	EMSL	12/8/07	< 0.00076	No	No	
ASBESTOS-ST1-12/8/07	030738542-0001	Southwest Area (sidewalk bridge level)	12/8/07	1	3.040	Asbestos	PCME	EMSL	12/10/07	< 0.00089	No	No	
ASBESTOS-ST2-12/8/07	030738542-0002	Southeast Area (sidewalk bridge level)	12/8/07	1	2.990	Asbestos	PCME	EMSL	12/10/07	< 0.00083	No	No	
ASBESTOS-ST4-12/8/07	030738542-0003	Northwest Area (street-level)	12/8/07	1	3.080	Asbestos	PCME	EMSL	12/10/07	< 0.00087	No	No	
ASBESTOS-ST5-12/8/07	030738542-0004	Firehouse #10 (roof level)	12/8/07	1	3.040	Asbestos	PCME	EMSL	12/10/07	< 0.00081	No	No	
ASBESTOS-ST10-12/8/07	030738542-0005	North Side Sidewalk Bridge	12/8/07	1	3.050	Asbestos	PCME	EMSL	12/10/07	< 0.00088	No	No	
ASBESTOS-ST11-12/8/07	030738542-0006	90 Trinity Place (roof level)	12/8/07	1	3.040	Asbestos	PCME	EMSL	12/10/07	< 0.00081	No	No	
ASBESTOS-ST12-12/8/07	030738542-0007	110 Greenwich Street (roof level)	12/8/07	1	2.960	Asbestos	PCME	EMSL	12/10/07	< 0.00083	No	No	
ASBESTOS-ST13-12/8/07	030738542-0008	Marriott Hotel, 38th Floor (roof level)	12/8/07	1	3.040	Asbestos	PCME	EMSL	12/10/07	< 0.00081	No	No	
ASBESTOS-ST14-12/8/07	030738542-0009	West Face - South end at corner (scaffolding level)	12/8/07	1	2.990	Asbestos	PCME	EMSL	12/10/07	< 0.00076	No	No	
ASBESTOS-ST15-12/8/07	030738542-0010	South Face - East end at corner (scaffolding level)	12/8/07	1	3.010	Asbestos	PCME	EMSL	12/10/07	< 0.00076	No	No	
ASBESTOS-ST16-12/8/07	030738542-0011	East Face - North end at corner (scaffolding level)	12/8/07	1	3.010	Asbestos	PCME	EMSL	12/10/07	< 0.00076	No	No	
ASBESTOS-ST17-12/8/07	030738542-0012	North Face - West end at corner (scaffolding level)	12/8/07	1	2.970	Asbestos	PCME	EMSL	12/10/07	< 0.00071	No	No	
ASBESTOS-ST1-12/9/07	030738545-0001	Southwest Area (sidewalk bridge level)	12/9/07	1	2.990	Asbestos	PCME	EMSL	12/10/07	< 0.00083	No	No	
ASBESTOS-ST2-12/9/07	030738545-0002	Southeast Area (sidewalk bridge level)	12/9/07	1	2.930	Asbestos	PCME	EMSL	12/10/07	< 0.00084	No	No	
ASBESTOS-ST4-12/9/07	030738545-0003	Northwest Area (street-level)	12/9/07	1	3.210	Asbestos	PCME	EMSL	12/10/07	< 0.00077	No	No	
ASBESTOS-ST5-12/9/07	030738545-0004	Firehouse #10 (roof level)	12/9/07	1	2.940	Asbestos	PCME	EMSL	12/10/07	< 0.00084	No	No	
ASBESTOS-ST10-12/9/07	030738545-0005	North Side Sidewalk Bridge	12/9/07	1	3.130	Asbestos	PCME	EMSL	12/10/07	< 0.00079	No	No	
ASBESTOS-ST11-12/9/07	030738545-0006	90 Trinity Place (roof level)	12/9/07	1	3.150	Asbestos	PCME	EMSL	12/10/07	< 0.00078	No	No	
ASBESTOS-ST12-12/9/07	030738545-0007	110 Greenwich Street (roof level)	12/9/07	1	3.020	Asbestos	PCME	EMSL	12/10/07	< 0.00082	No	No	
ASBESTOS-ST13-12/9/07	030738545-0008	Marriott Hotel, 38th Floor (roof level)	12/9/07	1	3.300	Asbestos	PCME	EMSL	12/10/07	< 0.00075	No	No	
ASBESTOS-ST14-12/9/07	030738545-0009	West Face - South end at corner (scaffolding level)	12/9/07	1	3.140	Asbestos	PCME	EMSL	12/10/07	< 0.00067	No	No	
ASBESTOS-ST15-12/9/07	030738545-0010	South Face - East end at corner (scaffolding level)	12/9/07	1	3.130	Asbestos	PCME	EMSL	12/10/07	< 0.00068	No	No	
ASBESTOS-ST16-12/9/07	030738545-0011	East Face - North end at corner (scaffolding level)	12/9/07	1	3.010	Asbestos	PCME	EMSL	12/10/07	< 0.00070	No	No	
ASBESTOS-ST17-12/9/07	030738545-0012	North Face - West end at corner (scaffolding level)	12/9/07	1	2.990	Asbestos	PCME	EMSL	12/10/07	< 0.00071	No	No	