

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-12/10/07	030738637-0001	Southwest Area (sidewalk bridge level)	12/10/07	1	3.200	Asbestos	PCME	EMSL	12/11/07	< 0.00085	No	No	
ASBESTOS-ST2-12/10/07	030738637-0002	Southeast Area (sidewalk bridge level)	12/10/07	1	3.180	Asbestos	PCME	EMSL	12/11/07	< 0.00082	No	No	
ASBESTOS-ST4-12/10/07	030738637-0003	Northwest Area (street-level)	12/10/07	1	3.260	Asbestos	PCME	EMSL	12/11/07	< 0.00079	No	No	
ASBESTOS-ST5-12/10/07	030738637-0004	Firehouse #10 (roof level)	12/10/07	1	3.040	Asbestos	PCME	EMSL	12/11/07	< 0.00082	No	No	
ASBESTOS-ST10-12/10/07	030738637-0005	North Side Sidewalk Bridge	12/10/07	1	3.250	Asbestos	PCME	EMSL	12/11/07	< 0.00079	No	No	
ASBESTOS-ST11-12/10/07	030738637-0006	90 Trinity Place (roof level)	12/10/07	1	3.050	Asbestos	PCME	EMSL	12/11/07	< 0.00081	No	No	
ASBESTOS-ST12-12/10/07	030738637-0007	110 Greenwich Street (roof level)	12/10/07	1	2.960	Asbestos	PCME	EMSL	12/11/07	< 0.00081	No	No	
ASBESTOS-ST13-12/10/07	030738637-0008	Marriott Hotel, 38th Floor (roof level)	12/10/07	1	3.010	Asbestos	PCME	EMSL	12/11/07	< 0.00085	No	No	
ASBESTOS-ST14-12/10/07	030738637-0009	West Face - South end at corner (scaffolding level)	12/10/07	1	2.610	Asbestos	PCME	EMSL	12/11/07	< 0.00068	No	No	
ASBESTOS-ST15-12/10/07	030738637-0010	South Face - East end at corner (scaffolding level)	12/10/07	1	2.540	Asbestos	PCME	EMSL	12/11/07	< 0.00070	No	No	
ASBESTOS-ST16-12/10/07	030738637-0011	East Face - North end at corner (scaffolding level)	12/10/07	1	2.610	Asbestos	PCME	EMSL	12/11/07	< 0.00069	No	No	
ASBESTOS-ST17-12/10/07	030738637-0012	North Face - West end at corner (scaffolding level)	12/10/07	1	2.580	Asbestos	PCME	EMSL	12/11/07	< 0.00069	No	No	
ASBESTOS-ST1-12/11/07	030738722-0001	Southwest Area (sidewalk bridge level)	12/11/07	1	3.040	Asbestos	PCME	EMSL	12/12/07	< 0.00076	No	No	
ASBESTOS-ST2-12/11/07	030738722-0002	Southeast Area (sidewalk bridge level)	12/11/07	1	2.990	Asbestos	PCME	EMSL	12/12/07	< 0.00080	No	No	
ASBESTOS-ST4-12/11/07	030738722-0003	Northwest Area (street-level)	12/11/07	1	3.080	Asbestos	PCME	EMSL	12/12/07	< 0.00078	No	No	
ASBESTOS-ST5-12/11/07	030738722-0004	Firehouse #10 (roof level)	12/11/07	1	3.040	Asbestos	PCME	EMSL	12/12/07	< 0.00080	No	No	
ASBESTOS-ST10-12/11/07	030738722-0005	North Side Sidewalk Bridge	12/11/07	1	3.050	Asbestos	PCME	EMSL	12/12/07	< 0.00077	No	No	
ASBESTOS-ST11-12/11/07	030738722-0006	90 Trinity Place (roof level)	12/11/07	1	3.040	Asbestos	PCME	EMSL	12/12/07	< 0.00081	No	No	
ASBESTOS-ST12-12/11/07	030738722-0007	110 Greenwich Street (roof level)	12/11/07	1	2.960	Asbestos	PCME	EMSL	12/12/07	< 0.00081	No	No	
ASBESTOS-ST13-12/11/07	030738722-0008	Marriott Hotel, 38th Floor (roof level)	12/11/07	1	3.040	Asbestos	PCME	EMSL	12/12/07	< 0.00082	No	No	
ASBESTOS-ST14-12/11/07	030738722-0009	West Face - South end at corner (scaffolding level)	12/11/07	1	2.570	Asbestos	PCME	EMSL	12/12/07	< 0.00070	No	No	
ASBESTOS-ST15-12/11/07	030738722-0010	South Face - East end at corner (scaffolding level)	12/11/07	1	2.580	Asbestos	PCME	EMSL	12/12/07	< 0.00072	No	No	
ASBESTOS-ST16-12/11/07	030738722-0011	East Face - North end at corner (scaffolding level)	12/11/07	1	2.580	Asbestos	PCME	EMSL	12/12/07	< 0.00070	No	No	
ASBESTOS-ST17-12/11/07	030738722-0012	North Face - West end at corner (scaffolding level)	12/11/07	1	2.540	Asbestos	PCME	EMSL	12/12/07	< 0.00067	No	No	
ASBESTOS-ST1-12/12/07	030738846-0001	Southwest Area (sidewalk bridge level)	12/12/07	1	2.980	Asbestos	PCME	EMSL	12/13/07	< 0.00083	No	No	
ASBESTOS-ST2-12/12/07	030738846-0002	Southeast Area (sidewalk bridge level)	12/12/07	1	2.990	Asbestos	PCME	EMSL	12/13/07	< 0.00083	No	No	
ASBESTOS-ST4-12/12/07	030738846-0003	Northwest Area (street-level)	12/12/07	1	3.040	Asbestos	PCME	EMSL	12/13/07	< 0.00081	No	No	
ASBESTOS-ST5-12/12/07	030738846-0004	Firehouse #10 (roof level)	12/12/07	1	2.920	Asbestos	PCME	EMSL	12/13/07	< 0.00085	No	No	
ASBESTOS-ST10-12/12/07	030738846-0005	North Side Sidewalk Bridge	12/12/07	1	3.020	Asbestos	PCME	EMSL	12/13/07	< 0.00082	No	No	
ASBESTOS-ST11-12/12/07	030738846-0006	90 Trinity Place (roof level)	12/12/07	1	3.010	Asbestos	PCME	EMSL	12/13/07	< 0.00082	No	No	
ASBESTOS-ST12-12/12/07	030738846-0007	110 Greenwich Street (roof level)	12/12/07	1	3.040	Asbestos	PCME	EMSL	12/13/07	< 0.00081	No	No	
ASBESTOS-ST13-12/12/07	030738846-0008	Marriott Hotel, 38th Floor (roof level)	12/12/07	1	3.050	Asbestos	PCME	EMSL	12/13/07	< 0.00081	No	No	
ASBESTOS-ST14-12/12/07	030738846-0009	West Face - South end at corner (scaffolding level)	12/12/07	1	3.040	Asbestos	PCME	EMSL	12/13/07	< 0.00081	No	No	
ASBESTOS-ST15-12/12/07	030738846-0010	South Face - East end at corner (scaffolding level)	12/12/07	1	2.920	Asbestos	PCME	EMSL	12/13/07	< 0.00085	No	No	
ASBESTOS-ST16-12/12/07	030738846-0011	East Face - North end at corner (scaffolding level)	12/12/07	1	3.090	Asbestos	PCME	EMSL	12/13/07	< 0.00080	No	No	
ASBESTOS-ST17-12/12/07	030738846-0012	North Face - West end at corner (scaffolding level)	12/12/07	1	3.010	Asbestos	PCME	EMSL	12/13/07	< 0.00082	No	No	