

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-12/12/08	030843617-0001	Southwest Area (sidewalk bridge level)	12/12/08	1	3.060	Asbestos	PCME	EMSL	12/13/08	< 0.00081	No	No	
ASBESTOS-ST2-12/12/08	030843617-0002	Southeast Area (sidewalk bridge level)	12/12/08	1	3.110	Asbestos	PCME	EMSL	12/13/08	< 0.00079	No	No	
ASBESTOS-ST4-12/12/08	030843617-0003	Northwest Area (street-level)	12/12/08	1	3.150	Asbestos	PCME	EMSL	12/13/08	< 0.00078	No	No	
ASBESTOS-ST5-12/12/08	030843617-0004	Firehouse #10 (roof level)	12/12/08	1	2.990	Asbestos	PCME	EMSL	12/13/08	< 0.00083	No	No	
ASBESTOS-ST10-12/12/08	030843617-0005	North Side Sidewalk Bridge	12/12/08	1	3.140	Asbestos	PCME	EMSL	12/13/08	< 0.00079	No	No	
ASBESTOS-ST11-12/12/08	030843617-0006	90 Trinity Place (roof level)	12/12/08	1	2.990	Asbestos	PCME	EMSL	12/13/08	< 0.00083	No	No	
ASBESTOS-ST12-12/12/08	030843617-0007	110 Greenwich Street (roof level)	12/12/08	1	2.950	Asbestos	PCME	EMSL	12/13/08	< 0.00084	No	No	
ASBESTOS-ST13-12/12/08	030843617-0008	Marriott Hotel, 38th Floor (roof level)	12/12/08	1	3.000	Asbestos	PCME	EMSL	12/13/08	< 0.00082	No	No	
ASBESTOS-ST14-12/12/08	030843617-0009	West Face - South end at corner (scaffolding level)	12/12/08	1	2.970	Asbestos	PCME	EMSL	12/13/08	< 0.00083	No	No	
ASBESTOS-ST15-12/12/08	030843617-0010	South Face - East end at corner (scaffolding level)	12/12/08	1	2.980	Asbestos	PCME	EMSL	12/13/08	< 0.00083	No	No	
ASBESTOS-ST16-12/12/08	030843617-0011	East Face - North end at corner (scaffolding level)	12/12/08	1	2.950	Asbestos	PCME	EMSL	12/13/08	< 0.00084	No	No	
ASBESTOS-ST17-12/12/08	030843617-0012	North Face - West end at corner (scaffolding level)	12/12/08	1	2.900	Asbestos	PCME	EMSL	12/13/08	< 0.00085	No	No	
ASBESTOS-ST1-12/13/08	030843707-0001	Southwest Area (sidewalk bridge level)	12/13/08	1	3.040	Asbestos	PCME	EMSL	12/15/08	< 0.00081	No	No	
ASBESTOS-ST2-12/13/08	030843707-0002	Southeast Area (sidewalk bridge level)	12/13/08	1	2.960	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST4-12/13/08	030843707-0003	Northwest Area (street-level)	12/13/08	1	2.920	Asbestos	PCME	EMSL	12/15/08	< 0.00085	No	No	
ASBESTOS-ST5-12/13/08	030843707-0004	Firehouse #10 (roof level)	12/13/08	1	3.080	Asbestos	PCME	EMSL	12/15/08	< 0.00080	No	No	
ASBESTOS-ST10-12/13/08	030843707-0005	North Side Sidewalk Bridge	12/13/08	1	2.970	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST11-12/13/08	030843707-0006	90 Trinity Place (roof level)	12/13/08	1	2.980	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST12-12/13/08	030843707-0007	110 Greenwich Street (roof level)	12/13/08	1	2.960	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST13-12/13/08	030843707-0008	Marriott Hotel, 38th Floor (roof level)	12/13/08	1	3.050	Asbestos	PCME	EMSL	12/15/08	< 0.00081	No	No	
ASBESTOS-ST14-12/13/08	030843707-0009	West Face - South end at corner (scaffolding level)	12/13/08	1	2.960	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST15-12/13/08	030843707-0010	South Face - East end at corner (scaffolding level)	12/13/08	1	2.930	Asbestos	PCME	EMSL	12/15/08	< 0.00084	No	No	
ASBESTOS-ST16-12/13/08	030843707-0011	East Face - North end at corner (scaffolding level)	12/13/08	1	2.870	Asbestos	PCME	EMSL	12/15/08	< 0.00086	No	No	
ASBESTOS-ST17-12/13/08	030843707-0012	North Face - West end at corner (scaffolding level)	12/13/08	1	2.980	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	