

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
										Target Air Quality Levels			
										EPA Site Specific Trigger Levels			
ASBESTOS-ST1-12/14/08	030843708-0001	Southwest Area (sidewalk bridge level)	12/14/08	1	3.050	Asbestos	PCME	EMSL	12/15/08	< 0.00081	No	No	
ASBESTOS-ST2-12/14/08	030843708-0002	Southeast Area (sidewalk bridge level)	12/14/08	1	3.020	Asbestos	PCME	EMSL	12/15/08	< 0.00082	No	No	
ASBESTOS-ST4-12/14/08	030843708-0003	Northwest Area (street-level)	12/14/08	1	3.120	Asbestos	PCME	EMSL	12/15/08	< 0.00079	No	No	
ASBESTOS-ST5-12/14/08	030843708-0004	Firehouse #10 (roof level)	12/14/08	1	2.980	Asbestos	PCME	EMSL	12/15/08	< 0.00083	No	No	
ASBESTOS-ST10-12/14/08	030843708-0005	North Side Sidewalk Bridge	12/14/08	1	3.000	Asbestos	PCME	EMSL	12/15/08	< 0.00082	No	No	
ASBESTOS-ST11-12/14/08	030843708-0006	90 Trinity Place (roof level)	12/14/08	1	3.000	Asbestos	PCME	EMSL	12/15/08	< 0.00082	No	No	
ASBESTOS-ST12-12/14/08	030843708-0007	110 Greenwich Street (roof level)	12/14/08	1	3.000	Asbestos	PCME	EMSL	12/15/08	< 0.00082	No	No	
ASBESTOS-ST13-12/14/08	030843708-0008	Marriott Hotel, 38th Floor (roof level)	12/14/08	1	2.930	Asbestos	PCME	EMSL	12/15/08	< 0.00084	No	No	
ASBESTOS-ST14-12/14/08	030843708-0009	West Face - South end at corner (scaffolding level)	12/14/08	1	3.160	Asbestos	PCME	EMSL	12/15/08	< 0.00078	No	No	
ASBESTOS-ST15-12/14/08	030843708-0010	South Face - East end at corner (scaffolding level)	12/14/08	1	3.250	Asbestos	PCME	EMSL	12/15/08	< 0.00076	No	No	
ASBESTOS-ST16-12/14/08	030843708-0011	East Face - North end at corner (scaffolding level)	12/14/08	1	3.180	Asbestos	PCME	EMSL	12/15/08	< 0.00078	No	No	
ASBESTOS-ST17-12/14/08	030843708-0012	North Face - West end at corner (scaffolding level)	12/14/08	1	3.170	Asbestos	PCME	EMSL	12/15/08	< 0.00078	No	No	
ASBESTOS-ST1-12/15/08	030843831-0001	Southwest Area (sidewalk bridge level)	12/15/08	1	3.010	Asbestos	PCME	EMSL	12/16/08	< 0.00082	No	No	
ASBESTOS-ST2-12/15/08	030843831-0002	Southeast Area (sidewalk bridge level)	12/15/08	1	2.980	Asbestos	PCME	EMSL	12/16/08	< 0.00083	No	No	
ASBESTOS-ST4-12/15/08	030843831-0003	Northwest Area (street-level)	12/15/08	1	3.080	Asbestos	PCME	EMSL	12/16/08	< 0.00080	No	No	
ASBESTOS-ST5-12/15/08	030843831-0004	Firehouse #10 (roof level)	12/15/08	1	2.990	Asbestos	PCME	EMSL	12/16/08	< 0.00083	No	No	
ASBESTOS-ST10-12/15/08	030843831-0005	North Side Sidewalk Bridge	12/15/08	1	3.060	Asbestos	PCME	EMSL	12/16/08	< 0.00081	No	No	
ASBESTOS-ST11-12/15/08	030843831-0006	90 Trinity Place (roof level)	12/15/08	1	2.990	Asbestos	PCME	EMSL	12/16/08	< 0.00083	No	No	
ASBESTOS-ST12-12/15/08	030843831-0007	110 Greenwich Street (roof level)	12/15/08	1	2.960	Asbestos	PCME	EMSL	12/16/08	< 0.00083	No	No	
ASBESTOS-ST13-12/15/08	030843831-0008	Marriott Hotel, 38th Floor (roof level)	12/15/08	1	3.030	Asbestos	PCME	EMSL	12/16/08	< 0.00081	No	No	
ASBESTOS-ST14-12/15/08	030843831-0009	West Face - South end at corner (scaffolding level)	12/15/08	1	3.040	Asbestos	PCME	EMSL	12/16/08	< 0.00081	No	No	
ASBESTOS-ST15-12/15/08	030843831-0010	South Face - East end at corner (scaffolding level)	12/15/08	1	3.020	Asbestos	PCME	EMSL	12/16/08	< 0.00082	No	No	
ASBESTOS-ST16-12/15/08	030843831-0011	East Face - North end at corner (scaffolding level)	12/15/08	1	3.030	Asbestos	PCME	EMSL	12/16/08	< 0.00081	No	No	
ASBESTOS-ST17-12/15/08	030843831-0012	North Face - West end at corner (scaffolding level)	12/15/08	1	3.010	Asbestos	PCME	EMSL	12/16/08	< 0.00082	No	No	
ASBESTOS-ST1-12/16/08	030843984-0001	Southwest Area (sidewalk bridge level)	12/16/08	1	3.040	Asbestos	PCME	EMSL	12/17/08	< 0.00081	No	No	
ASBESTOS-ST2-12/16/08	030843984-0002	Southeast Area (sidewalk bridge level)	12/16/08	1	3.090	Asbestos	PCME	EMSL	12/17/08	< 0.00087	No	No	
ASBESTOS-ST4-12/16/08	030843984-0003	Northwest Area (street-level)	12/16/08	1	3.130	Asbestos	PCME	EMSL	12/17/08	< 0.00086	No	No	
ASBESTOS-ST5-12/16/08	030843984-0004	Firehouse #10 (roof level)	12/16/08	1	3.000	Asbestos	PCME	EMSL	12/17/08	< 0.00082	No	No	
ASBESTOS-ST10-12/16/08	030843984-0005	North Side Sidewalk Bridge	12/16/08	1	3.120	Asbestos	PCME	EMSL	12/17/08	< 0.00086	No	No	
ASBESTOS-ST11-12/16/08	030843984-0006	90 Trinity Place (roof level)	12/16/08	1	3.040	Asbestos	PCME	EMSL	12/17/08	< 0.00081	No	No	
ASBESTOS-ST12-12/16/08	030843984-0007	110 Greenwich Street (roof level)	12/16/08	1	3.090	Asbestos	PCME	EMSL	12/17/08	< 0.00087	No	No	
ASBESTOS-ST13-12/16/08	030843984-0008	Marriott Hotel, 38th Floor (roof level)	12/16/08	1	3.050	Asbestos	PCME	EMSL	12/17/08	< 0.00081	No	No	
ASBESTOS-ST14-12/16/08	030843984-0009	West Face - South end at corner (scaffolding level)	12/16/08	1	3.100	Asbestos	PCME	EMSL	12/17/08	< 0.00087	No	No	
ASBESTOS-ST15-12/16/08	030843984-0010	South Face - East end at corner (scaffolding level)	12/16/08	1	3.070	Asbestos	PCME	EMSL	12/17/08	< 0.00088	No	No	
ASBESTOS-ST16-12/16/08	030843984-0011	East Face - North end at corner (scaffolding level)	12/16/08	1	3.090	Asbestos	PCME	EMSL	12/17/08	< 0.00087	No	No	
ASBESTOS-ST17-12/16/08	030843984-0012	North Face - West end at corner (scaffolding level)	12/16/08	1	3.030	Asbestos	PCME	EMSL	12/17/08	< 0.00081	No	No	