

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										0.0009	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-12/15/06	030640707-0001	Southwest Area (sidewalk bridge level)	12/15/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST2-12/15/06	030640707-0002	Southeast Area (sidewalk bridge level)	12/15/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST4-12/15/06	030640707-0003	Northwest Area (street-level)	12/15/06	1	2.970	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST5-12/15/06	030640707-0004	Firehouse #10 (roof level)	12/15/06	1	2.960	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST10-12/15/06	030640707-0005	North Side Sidewalk Bridge	12/15/06	1	3.010	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST11-12/15/06	030640707-0006	90 Trinity Place (roof level)	12/15/06	1	3.030	Asbestos	PCME	EMSL	12/18/06	< 0.00081	No	No	
ASBESTOS-ST12-12/15/06	030640707-0007	110 Greenwich Street (roof level)	12/15/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST13-12/15/06	030640707-0008	Marriott Hotel, 38th Floor (roof level)	12/15/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST14-12/15/06	030640707-0009	West Face - South end at corner (scaffolding level)	12/15/06	1	2.960	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST15-12/15/06	030640707-0010	South Face - East end at corner (scaffolding level)	12/15/06	1	3.040	Asbestos	PCME	EMSL	12/18/06	< 0.00081	No	No	
ASBESTOS-ST16-12/15/06	030640707-0011	East Face - North end at corner (scaffolding level)	12/15/06	1	3.040	Asbestos	PCME	EMSL	12/18/06	< 0.00081	No	No	
ASBESTOS-ST17-12/15/06	030640707-0012	North Face - West end at corner (scaffolding level)	12/15/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST1-12/16/06	030640706-0001	Southwest Area (sidewalk bridge level)	12/16/06	1	3.030	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST2-12/16/06	030640706-0002	Southeast Area (sidewalk bridge level)	12/16/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST4-12/16/06	030640706-0003	Northwest Area (street-level)	12/16/06	1	3.010	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST5-12/16/06	030640706-0004	Firehouse #10 (roof level)	12/16/06	1	2.980	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST10-12/16/06	030640706-0005	North Side Sidewalk Bridge	12/16/06	1	3.010	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST11-12/16/06	030640706-0006	90 Trinity Place (roof level)	12/16/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST12-12/16/06	030640706-0007	110 Greenwich Street (roof level)	12/16/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST13-12/16/06	030640706-0008	Marriott Hotel, 38th Floor (roof level)	12/16/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST14-12/16/06	030640706-0009	West Face - South end at corner (scaffolding level)	12/16/06	1	2.960	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST15-12/16/06	030640706-0010	South Face - East end at corner (scaffolding level)	12/16/06	1	3.010	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST16-12/16/06	030640706-0011	East Face - North end at corner (scaffolding level)	12/16/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00089	No	No	
ASBESTOS-ST17-12/16/06	030640706-0012	North Face - West end at corner (scaffolding level)	12/16/06	1	2.900	Asbestos	PCME	EMSL	12/18/06	< 0.00085	No	No	
ASBESTOS-ST1-12/17/06	030640705-0001	Southwest Area (sidewalk bridge level)	12/17/06	1	2.970	Asbestos	PCME	EMSL	12/18/06	< 0.00083	No	No	
ASBESTOS-ST2-12/17/06	030640705-0002	Southeast Area (sidewalk bridge level)	12/17/06	1	2.920	Asbestos	PCME	EMSL	12/18/06	< 0.00085	No	No	
ASBESTOS-ST4-12/17/06	030640705-0003	Northwest Area (street-level)	12/17/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST5-12/17/06	030640705-0004	Firehouse #10 (roof level)	12/17/06	1	3.160	Asbestos	PCME	EMSL	12/18/06	< 0.00078	No	No	
ASBESTOS-ST10-12/17/06	030640705-0005	North Side Sidewalk Bridge	12/17/06	1	3.070	Asbestos	PCME	EMSL	12/18/06	< 0.00080	No	No	
ASBESTOS-ST11-12/17/06	030640705-0006	90 Trinity Place (roof level)	12/17/06	1	3.150	Asbestos	PCME	EMSL	12/18/06	< 0.00078	No	No	
ASBESTOS-ST12-12/17/06	030640705-0007	110 Greenwich Street (roof level)	12/17/06	1	3.090	Asbestos	PCME	EMSL	12/18/06	< 0.00080	No	No	
ASBESTOS-ST13-12/17/06	030640705-0008	Marriott Hotel, 38th Floor (roof level)	12/17/06	1	3.020	Asbestos	PCME	EMSL	12/18/06	< 0.00082	No	No	
ASBESTOS-ST14-12/17/06	030640705-0009	West Face - South end at corner (scaffolding level)	12/17/06	1	2.850	Asbestos	PCME	EMSL	12/18/06	< 0.00080	No	No	
ASBESTOS-ST15-12/17/06	030640705-0010	South Face - East end at corner (scaffolding level)	12/17/06	1	3.080	Asbestos	PCME	EMSL	12/18/06	< 0.00080	No	No	
ASBESTOS-ST16-12/17/06	030640705-0011	East Face - North end at corner (scaffolding level)	12/17/06	1	3.040	Asbestos	PCME	EMSL	12/18/06	< 0.00081	No	No	
ASBESTOS-ST17-12/17/06	030640705-0012	North Face - West end at corner (scaffolding level)	12/17/06	1	2.870	Asbestos	PCME	EMSL	12/18/06	< 0.00079	No	No	
ASBESTOS-ST1-12/18/06	030640868-0001	Southwest Area (sidewalk bridge level)	12/18/06	1	3.090	Asbestos	PCME	EMSL	12/19/06	< 0.00080	No	No	
ASBESTOS-ST2-12/18/06	030640868-0002	Southeast Area (sidewalk bridge level)	12/18/06	1	3.340	Asbestos	PCME	EMSL	12/19/06	< 0.00074	No	No	
ASBESTOS-ST4-12/18/06	030640868-0003	Northwest Area (street-level)	12/18/06	1	3.060	Asbestos	PCME	EMSL	12/19/06	< 0.00081	No	No	
ASBESTOS-ST5-12/18/06	030640868-0004	Firehouse #10 (roof level)	12/18/06	1	3.020	Asbestos	PCME	EMSL	12/19/06	< 0.00082	No	No	
ASBESTOS-ST10-12/18/06	030640868-0005	North Side Sidewalk Bridge	12/18/06	1	3.070	Asbestos	PCME	EMSL	12/19/06	< 0.00080	No	No	
ASBESTOS-ST11-12/18/06	030640868-0006	90 Trinity Place (roof level)	12/18/06	1	3.020	Asbestos	PCME	EMSL	12/19/06	< 0.00082	No	No	
ASBESTOS-ST12-12/18/06	030640868-0007	110 Greenwich Street (roof level)	12/18/06	1	3.020	Asbestos	PCME	EMSL	12/19/06	< 0.00082	No	No	
ASBESTOS-ST13-12/18/06	030640868-0008	Marriott Hotel, 38th Floor (roof level)	12/18/06	1	2.900	Asbestos	PCME	EMSL	12/19/06	< 0.00085	No	No	
ASBESTOS-ST14-12/18/06	030640868-0009	West Face - South end at corner (scaffolding level)	12/18/06	1	3.020	Asbestos	PCME	EMSL	12/19/06	< 0.00082	No	No	
ASBESTOS-ST15-12/18/06	030640868-0010	South Face - East end at corner (scaffolding level)	12/18/06	1	2.920	Asbestos	PCME	EMSL	12/19/06	< 0.00085	No	No	
ASBESTOS-ST16-12/18/06	030640868-0011	East Face - North end at corner (scaffolding level)	12/18/06	1	3.030	Asbestos	PCME	EMSL	12/19/06	< 0.00081	No	No	
ASBESTOS-ST17-12/18/06	030640868-0012	North Face - West end at corner (scaffolding level)	12/18/06	1	3.090	Asbestos	PCME	EMSL	12/19/06	< 0.00080	No	No	