

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-12/15/07	030739134-0001	Southwest Area (sidewalk bridge level)	12/15/07	1	3.000	Asbestos	PCME	EMSL	12/17/07	< 0.00082	No	No	
ASBESTOS-ST2-12/15/07	030739134-0002	Southeast Area (sidewalk bridge level)	12/15/07	1	3.040	Asbestos	PCME	EMSL	12/17/07	< 0.00081	No	No	
ASBESTOS-ST4-12/15/07	030739134-0003	Northwest Area (street-level)	12/15/07	1	3.140	Asbestos	PCME	EMSL	12/17/07	< 0.00079	No	No	
ASBESTOS-ST5-12/15/07	030739134-0004	Firehouse #10 (roof level)	12/15/07	1	3.140	Asbestos	PCME	EMSL	12/17/07	< 0.00079	No	No	
ASBESTOS-ST10-12/15/07	030739134-0005	North Side Sidewalk Bridge	12/15/07	1	3.090	Asbestos	PCME	EMSL	12/17/07	< 0.00080	No	No	
ASBESTOS-ST11-12/15/07	030739134-0006	90 Trinity Place (roof level)	12/15/07	1	3.040	Asbestos	PCME	EMSL	12/17/07	< 0.00081	No	No	
ASBESTOS-ST12-12/15/07	030739134-0007	110 Greenwich Street (roof level)	12/15/07	1	3.010	Asbestos	PCME	EMSL	12/17/07	< 0.00082	No	No	
ASBESTOS-ST13-12/15/07	030739134-0008	Marriott Hotel, 38th Floor (roof level)	12/15/07	1	3.070	Asbestos	PCME	EMSL	12/17/07	< 0.00080	No	No	
ASBESTOS-ST14-12/15/07	030739134-0009	West Face - South end at corner (scaffolding level)	12/15/07	1	2.430	Asbestos	PCME	EMSL	12/17/07	< 0.00087	No	No	
ASBESTOS-ST15-12/15/07	030739134-0010	South Face - East end at corner (scaffolding level)	12/15/07	1	2.590	Asbestos	PCME	EMSL	12/17/07	< 0.00088	No	No	
ASBESTOS-ST16-12/15/07	030739134-0011	East Face - North end at corner (scaffolding level)	12/15/07	1	2.470	Asbestos	PCME	EMSL	12/17/07	< 0.00086	No	No	
ASBESTOS-ST17-12/15/07	030739134-0012	North Face - West end at corner (scaffolding level)	12/15/07	1	2.460	Asbestos	PCME	EMSL	12/17/07	< 0.00086	No	No	
ASBESTOS-ST1-12/16/07	030739135-0001	Southwest Area (sidewalk bridge level)	12/16/07	1	3.010	Asbestos	PCME	EMSL	12/17/07	< 0.00082	No	No	
ASBESTOS-ST2-12/16/07	030739135-0002	Southeast Area (sidewalk bridge level)	12/16/07	1	3.070	Asbestos	PCME	EMSL	12/17/07	< 0.00080	No	No	
ASBESTOS-ST4-12/16/07	030739135-0003	Northwest Area (street-level)	12/16/07	1	3.060	Asbestos	PCME	EMSL	12/17/07	< 0.00081	No	No	
ASBESTOS-ST5-12/16/07	030739135-0004	Firehouse #10 (roof level)	12/16/07	1	3.150	Asbestos	PCME	EMSL	12/17/07	< 0.00085	No	No	
ASBESTOS-ST10-12/16/07	030739135-0005	North Side Sidewalk Bridge	12/16/07	1	3.110	Asbestos	PCME	EMSL	12/17/07	< 0.00087	No	No	
ASBESTOS-ST11-12/16/07	030739135-0006	90 Trinity Place (roof level)	12/16/07	1	3.000	Asbestos	PCME	EMSL	12/17/07	< 0.00082	No	No	
ASBESTOS-ST12-12/16/07	030739135-0007	110 Greenwich Street (roof level)	12/16/07	1	3.030	Asbestos	PCME	EMSL	12/17/07	< 0.00081	No	No	
ASBESTOS-ST13-12/16/07	030739135-0008	Marriott Hotel, 38th Floor (roof level)	12/16/07	1	3.010	Asbestos	PCME	EMSL	12/17/07	< 0.00082	No	No	
ASBESTOS-ST14-12/16/07	030739135-0009	West Face - South end at corner (scaffolding level)	12/16/07	1	3.900	Asbestos	PCME	EMSL	12/17/07	< 0.00084	No	No	
ASBESTOS-ST15-12/16/07	030739135-0010	South Face - East end at corner (scaffolding level)	12/16/07	1	3.770	Asbestos	PCME	EMSL	12/17/07	< 0.00087	No	No	
ASBESTOS-ST16-12/16/07	030739135-0011	East Face - North end at corner (scaffolding level)	12/16/07	1	3.870	Asbestos	PCME	EMSL	12/17/07	< 0.00085	No	No	
ASBESTOS-ST17-12/16/07	030739135-0012	North Face - West end at corner (scaffolding level)	12/16/07	1	3.910	Asbestos	PCME	EMSL	12/17/07	< 0.00084	No	No	
ASBESTOS-ST1-12/17/07	030739213-0001	Southwest Area (sidewalk bridge level)	12/17/07	1	2.830	Asbestos	PCME	EMSL	12/18/07	< 0.00087	No	No	
ASBESTOS-ST2-12/17/07	030739213-0002	Southeast Area (sidewalk bridge level)	12/17/07	1	2.990	Asbestos	PCME	EMSL	12/18/07	< 0.00083	No	No	
ASBESTOS-ST4-12/17/07	030739213-0003	Northwest Area (street-level)	12/17/07	1	3.040	Asbestos	PCME	EMSL	12/18/07	< 0.00081	No	No	
ASBESTOS-ST5-12/17/07	030739213-0004	Firehouse #10 (roof level)	12/17/07	1	3.040	Asbestos	PCME	EMSL	12/18/07	< 0.00081	No	No	
ASBESTOS-ST10-12/17/07	030739213-0005	North Side Sidewalk Bridge	12/17/07	1	3.040	Asbestos	PCME	EMSL	12/18/07	< 0.00081	No	No	
ASBESTOS-ST11-12/17/07	030739213-0006	90 Trinity Place (roof level)	12/17/07	1	3.000	Asbestos	PCME	EMSL	12/18/07	< 0.00082	No	No	
ASBESTOS-ST12-12/17/07	030739213-0007	110 Greenwich Street (roof level)	12/17/07	1	3.130	Asbestos	PCME	EMSL	12/18/07	< 0.00086	No	No	
ASBESTOS-ST13-12/17/07	030739213-0008	Marriott Hotel, 38th Floor (roof level)	12/17/07	1	3.020	Asbestos	PCME	EMSL	12/18/07	< 0.00082	No	No	
ASBESTOS-ST14-12/17/07	030739213-0009	West Face - South end at corner (scaffolding level)	12/17/07	1	2.280	Asbestos	PCME	EMSL	12/18/07	< 0.00087	No	No	
ASBESTOS-ST15-12/17/07	030739213-0010	South Face - East end at corner (scaffolding level)	12/17/07	1	2.290	Asbestos	PCME	EMSL	12/18/07	< 0.00086	No	No	
ASBESTOS-ST16-12/17/07	030739213-0011	East Face - North end at corner (scaffolding level)	12/17/07	1	2.300	Asbestos	PCME	EMSL	12/18/07	< 0.00086	No	No	
ASBESTOS-ST17-12/17/07	030739213-0012	North Face - West end at corner (scaffolding level)	12/17/07	1	2.300	Asbestos	PCME	EMSL	12/18/07	< 0.00086	No	No	