TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-1/15/2010	Southwest Area (sidewalk bridge level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST2-1/15/2010	Southeast Area (sidewalk bridge level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST4-1/15/2010	Northwest Area (street-level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-1/15/2010	Firehouse #10 (roof level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST11-1/15/2010	90 Trinity Place (roof level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-1/15/2010	110 Greenwich Street (roof level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-1/15/2010	Marriott Hotel, 38th Floor (roof level)	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST20-1/15/2010	Northeast Area, Sidewalk Bridge	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST200-1/15/2010	Station 20 Field Duplicate	1/15/10	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST1-1/16/2010	Southwest Area (sidewalk bridge level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-1/16/2010	Southeast Area (sidewalk bridge level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST4-1/16/2010	Northwest Area (street-level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST5-1/16/2010	Firehouse #10 (roof level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST11-1/16/2010	90 Trinity Place (roof level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-1/16/2010	110 Greenwich Street (roof level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-1/16/2010	Marriott Hotel, 38th Floor (roof level)	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST20-1/16/2010	Northeast Area, Sidewalk Bridge	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST200-1/16/2010	Station 20 Field Duplicate	1/16/10	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST1-1/17/2010	Southwest Area (sidewalk bridge level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST2-1/17/2010	Southeast Area (sidewalk bridge level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST4-1/17/2010	Northwest Area (street-level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST5-1/17/2010	Firehouse #10 (roof level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST11-1/17/2010	90 Trinity Place (roof level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-1/17/2010	110 Greenwich Street (roof level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST13-1/17/2010	Marriott Hotel, 38th Floor (roof level)	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST20-1/17/2010	Northeast Area, Sidewalk Bridge	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST200-1/17/2010	Station 20 Field Duplicate	1/17/10	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	