

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-1/22/2007	Southwest Area (sidewalk bridge level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST2-1/22/2007	Southeast Area (sidewalk bridge level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-1/22/2007	Northwest Area (street-level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST5-1/22/2007	Firehouse #10 (roof level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST100-1/22/2007	Station 10 Field Duplicate	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST11-1/22/2007	90 Trinity Place (roof level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST12-1/22/2007	110 Greenwich Street (roof level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST13-1/22/2007	Marriott Hotel, 38th Floor (roof level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST14-1/22/2007	West Face - South end at corner (scaffolding level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST15-1/22/2007	South Face - East end at corner (scaffolding level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST16-1/22/2007	East Face - North end at corner (scaffolding level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST17-1/22/2007	North Face - West end at corner (scaffolding level)	1/22/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-1/23/2007	Southeast Area (sidewalk bridge level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST4-1/23/2007	Northwest Area (street-level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-1/23/2007	Firehouse #10 (roof level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST100-1/23/2007	Station 10 Field Duplicate	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-1/23/2007	90 Trinity Place (roof level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST13-1/23/2007	Marriott Hotel, 38th Floor (roof level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST14-1/23/2007	West Face - South end at corner (scaffolding level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST15-1/23/2007	South Face - East end at corner (scaffolding level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-1/23/2007	East Face - North end at corner (scaffolding level)	1/23/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	

Note:

1. The PM 10 reading at Station 10 (North Side Sidewalk Bridge) on January 22, 2007 was not available on account of instrument malfunction.
2. The PM 10 readings at Station 1 (Southwest Area [sidewalk bridge level]), Station 10 (North Side Sidewalk Bridge), Station 12 (110 Greenwich Street [roof level]), and Station 17 (North Face - West end at corner [scaffolding level]) on January 23, 2007 were not available on account of instrument malfunction.