TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	1
PM10-ST1-3/10/2008	Southwest Area (sidewalk bridge level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-3/10/2008	Southeast Area (sidewalk bridge level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-3/10/2008	Northwest Area (street-level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST5-3/10/2008	Firehouse #10 (roof level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST10-3/10/2008	North Side Sidewalk Bridge	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-3/10/2008	Station 10 Field Duplicate	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST11-3/10/2008	90 Trinity Place (roof level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST12-3/10/2008	110 Greenwich Street (roof level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST14-3/10/2008	West Face - South end at corner (scaffolding level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-3/10/2008	South Face - East end at corner (scaffolding level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST16-3/10/2008	East Face - North end at corner (scaffolding level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-3/10/2008	North Face - West end at corner (scaffolding level)	3/10/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST1-3/11/2008	Southwest Area (sidewalk bridge level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST2-3/11/2008	Southeast Area (sidewalk bridge level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST4-3/11/2008	Northwest Area (street-level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST10-3/11/2008	North Side Sidewalk Bridge	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST100-3/11/2008	Station 10 Field Duplicate	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST11-3/11/2008	90 Trinity Place (roof level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST12-3/11/2008	110 Greenwich Street (roof level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST13-3/11/2008	Marriott Hotel, 38th Floor (roof level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST14-3/11/2008	West Face - South end at corner (scaffolding level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST15-3/11/2008	South Face - East end at corner (scaffolding level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST16-3/11/2008	East Face - North end at corner (scaffolding level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST17-3/11/2008	North Face - West end at corner (scaffolding level)	3/11/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	

- The PM 10 reading at Station 13 (Marriott Hotel, 38th Floor [roof level]) on March 10, 2008 was not available on account of instrument malfunction.
 The PM 10 reading at Station 5 (Firehouse #10 [roof level]) on March 11, 2008 was not available on account of instrument malfunction.