TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-4/13/2009	Southwest Area (sidewalk bridge level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-4/13/2009	Southeast Area (sidewalk bridge level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST4-4/13/2009	Northwest Area (street-level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-4/13/2009	Firehouse #10 (roof level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-4/13/2009	North Side Sidewalk Bridge	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST100-4/13/2009	Station 10 Field Duplicate	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-4/13/2009	90 Trinity Place (roof level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST12-4/13/2009	110 Greenwich Street (roof level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST13-4/13/2009	Marriott Hotel, 38th Floor (roof level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-4/13/2009	West Face - South end at corner (scaffolding level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST16-4/13/2009	East Face - North end at corner (scaffolding level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-4/13/2009	North Face - West end at corner (scaffolding level)	4/13/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-4/14/2009	Southwest Area (sidewalk bridge level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST2-4/14/2009	Southeast Area (sidewalk bridge level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST4-4/14/2009	Northwest Area (street-level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	59	No	No	
PM10-ST5-4/14/2009	Firehouse #10 (roof level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-4/14/2009	North Side Sidewalk Bridge	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST100-4/14/2009	Station 10 Field Duplicate	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST11-4/14/2009	90 Trinity Place (roof level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST12-4/14/2009	110 Greenwich Street (roof level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-4/14/2009	Marriott Hotel, 38th Floor (roof level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST14-4/14/2009	West Face - South end at corner (scaffolding level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST17-4/14/2009	North Face - West end at corner (scaffolding level)	4/14/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	

- The PM10 readings from Station 15 (South Face East end at corner [scaffolding level]) on April 13 and 14, 2009 were not available on account of instrument malfunction.
 The PM10 reading from Station 16 (East Face North end at corner [scaffolding level]) on April 14, 2009 was not available on account of instrument malfunction.