

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-4/14/2008	Southwest Area (sidewalk bridge level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST2-4/14/2008	Southeast Area (sidewalk bridge level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-4/14/2008	Northwest Area (street-level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST5-4/14/2008	Firehouse #10 (roof level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST10-4/14/2008	North Side Sidewalk Bridge	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST100-4/14/2008	Station 10 Field Duplicate	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST11-4/14/2008	90 Trinity Place (roof level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST12-4/14/2008	110 Greenwich Street (roof level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST13-4/14/2008	Marriott Hotel, 38th Floor (roof level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST14-4/14/2008	West Face - South end at corner (scaffolding level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST15-4/14/2008	South Face - East end at corner (scaffolding level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST16-4/14/2008	East Face - North end at corner (scaffolding level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST17-4/14/2008	North Face - West end at corner (scaffolding level)	4/14/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST1-4/15/2008	Southwest Area (sidewalk bridge level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST2-4/15/2008	Southeast Area (sidewalk bridge level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST4-4/15/2008	Northwest Area (street-level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST5-4/15/2008	Firehouse #10 (roof level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST100-4/15/2008	Station 10 Field Duplicate	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-4/15/2008	90 Trinity Place (roof level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-4/15/2008	110 Greenwich Street (roof level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-4/15/2008	Marriott Hotel, 38th Floor (roof level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-4/15/2008	West Face - South end at corner (scaffolding level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-4/15/2008	South Face - East end at corner (scaffolding level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST16-4/15/2008	East Face - North end at corner (scaffolding level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-4/15/2008	North Face - West end at corner (scaffolding level)	4/15/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

1. The PM 10 reading at Station 10 (North Side Sidewalk Bridge) on April 15, 2008 was not available on account of instrument malfunction.