TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-6/20/2007	Southwest Area (sidewalk bridge level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-6/20/2007	Southeast Area (sidewalk bridge level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	58	No	No	
PM10-ST4-6/20/2007	Northwest Area (street-level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST5-6/20/2007	Firehouse #10 (roof level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-6/20/2007	North Side Sidewalk Bridge	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST11-6/20/2007	90 Trinity Place (roof level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST12-6/20/2007	110 Greenwich Street (roof level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST13-6/20/2007	Marriott Hotel, 38th Floor (roof level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-6/20/2007	West Face - South end at corner (scaffolding level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-6/20/2007	South Face - East end at corner (scaffolding level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST16-6/20/2007	East Face - North end at corner (scaffolding level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST17-6/20/2007	North Face - West end at corner (scaffolding level)	6/20/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST1-6/21/2007	Southwest Area (sidewalk bridge level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST2-6/21/2007	Southeast Area (sidewalk bridge level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-6/21/2007	Northwest Area (street-level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST5-6/21/2007	Firehouse #10 (roof level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST10-6/21/2007	North Side Sidewalk Bridge	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST11-6/21/2007	90 Trinity Place (roof level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST12-6/21/2007	110 Greenwich Street (roof level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-6/21/2007	Marriott Hotel, 38th Floor (roof level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST14-6/21/2007	West Face - South end at corner (scaffolding level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST15-6/21/2007	South Face - East end at corner (scaffolding level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST16-6/21/2007	East Face - North end at corner (scaffolding level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST17-6/21/2007	North Face - West end at corner (scaffolding level)	6/21/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	

Note:
1. The PM 10 readings at Station 100 (Station 10 Field Duplicate) on June 20 and 21, 2007 were not available on account of instrument malfunction.