TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-6/21/2006	Southwest Area (sidewalk bridge level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST2-6/21/2006	Southeast Area (sidewalk bridge level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	40	No	No	
PM10-ST4-6/21/2006	Northwest Area (street-level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST5-6/21/2006	Firehouse #10 (roof level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST10-6/21/2006	North Side Sidewalk Bridge	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST100-6/21/2006	Station 10 Field Duplicate	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST11-6/21/2006	90 Trinity Place (roof level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST12-6/21/2006	110 Greenwich Street (roof level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-6/21/2006	Marriott Hotel, 38th Floor (roof level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST14-6/21/2006	West Face - South end at corner (scaffolding level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST15-6/21/2006	South Face - East end at corner (scaffolding level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST16-6/21/2006	East Face - North end at corner (scaffolding level)	6/21/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST1-6/22/2006	Southwest Area (sidewalk bridge level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST2-6/22/2006	Southeast Area (sidewalk bridge level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	49	No	No	
PM10-ST4-6/22/2006	Northwest Area (street-level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST5-6/22/2006	Firehouse #10 (roof level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST10-6/22/2006	North Side Sidewalk Bridge	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	48	No	No	
PM10-ST100-6/22/2006	Station 10 Field Duplicate	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST11-6/22/2006	90 Trinity Place (roof level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST12-6/22/2006	110 Greenwich Street (roof level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST13-6/22/2006	Marriott Hotel, 38th Floor (roof level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST14-6/22/2006	West Face - South end at corner (scaffolding level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST15-6/22/2006	South Face - East end at corner (scaffolding level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST16-6/22/2006	East Face - North end at corner (scaffolding level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST17-6/22/2006	North Face - West end at corner (scaffolding level)	6/22/06	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	

Note: 1. The PM 10 reading at Station 17 (North Face - West end at corner [scaffolding level]) on June 21, 2006 was not available on account of instrument malfunction.