

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-7/10/2009	Southwest Area (sidewalk bridge level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-7/10/2009	Southeast Area (sidewalk bridge level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST4-7/10/2009	Northwest Area (street-level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST5-7/10/2009	Firehouse #10 (roof level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST10-7/10/2009	North Side Sidewalk Bridge	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST11-7/10/2009	90 Trinity Place (roof level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST12-7/10/2009	110 Greenwich Street (roof level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST13-7/10/2009	Marriott Hotel, 38th Floor (roof level)	7/10/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST1-7/11/2009	Southwest Area (sidewalk bridge level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST2-7/11/2009	Southeast Area (sidewalk bridge level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST4-7/11/2009	Northwest Area (street-level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-7/11/2009	Firehouse #10 (roof level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-7/11/2009	North Side Sidewalk Bridge	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST100-7/11/2009	Station 10 Field Duplicate	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST11-7/11/2009	90 Trinity Place (roof level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST12-7/11/2009	110 Greenwich Street (roof level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-7/11/2009	Marriott Hotel, 38th Floor (roof level)	7/11/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-7/12/2009	Southwest Area (sidewalk bridge level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST2-7/12/2009	Southeast Area (sidewalk bridge level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST4-7/12/2009	Northwest Area (street-level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-7/12/2009	Firehouse #10 (roof level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-7/12/2009	North Side Sidewalk Bridge	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-7/12/2009	Station 10 Field Duplicate	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST11-7/12/2009	90 Trinity Place (roof level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-7/12/2009	110 Greenwich Street (roof level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST13-7/12/2009	Marriott Hotel, 38th Floor (roof level)	7/12/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	

Note:

The PM10 reading from Station 100 (Station 10 Field Duplicate) on July 10, 2009 was not available on account of instrument malfunction.