

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-7/16/2008	Southwest Area (sidewalk bridge level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST2-7/16/2008	Southeast Area (sidewalk bridge level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST4-7/16/2008	Northwest Area (street-level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	36	No	No	
PM10-ST5-7/16/2008	Firehouse #10 (roof level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST10-7/16/2008	North Side Sidewalk Bridge	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST11-7/16/2008	90 Trinity Place (roof level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST12-7/16/2008	110 Greenwich Street (roof level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST13-7/16/2008	Marriott Hotel, 38th Floor (roof level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST14-7/16/2008	West Face - South end at corner (scaffolding level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST15-7/16/2008	South Face - East end at corner (scaffolding level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST16-7/16/2008	East Face - North end at corner (scaffolding level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST17-7/16/2008	North Face - West end at corner (scaffolding level)	7/16/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST2-7/17/2008	Southeast Area (sidewalk bridge level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	45	No	No	
PM10-ST4-7/17/2008	Northwest Area (street-level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	52	No	No	
PM10-ST5-7/17/2008	Firehouse #10 (roof level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST10-7/17/2008	North Side Sidewalk Bridge	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST11-7/17/2008	90 Trinity Place (roof level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST12-7/17/2008	110 Greenwich Street (roof level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST13-7/17/2008	Marriott Hotel, 38th Floor (roof level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST14-7/17/2008	West Face - South end at corner (scaffolding level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST15-7/17/2008	South Face - East end at corner (scaffolding level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST16-7/17/2008	East Face - North end at corner (scaffolding level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST17-7/17/2008	North Face - West end at corner (scaffolding level)	7/17/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	

Notes:

1. The PM 10 reading at Station 1 (Southwest Area [sidewalk bridge level]) on July 17, 2008 was not available on account of instrument malfunction.
2. The PM 10 readings at Station 100 (Station 10 Field Duplicate) on July 16 and 17, 2008 were not available on account of instrument malfunction.