

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-9/15/2008	Southwest Area (sidewalk bridge level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST2-9/15/2008	Southeast Area (sidewalk bridge level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST4-9/15/2008	Northwest Area (street-level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST5-9/15/2008	Firehouse #10 (roof level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST10-9/15/2008	North Side Sidewalk Bridge	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST100-9/15/2008	Station 10 Field Duplicate	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST11-9/15/2008	90 Trinity Place (roof level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-9/15/2008	110 Greenwich Street (roof level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-9/15/2008	Marriott Hotel, 38th Floor (roof level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST14-9/15/2008	West Face - South end at corner (scaffolding level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-9/15/2008	South Face - East end at corner (scaffolding level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-9/15/2008	East Face - North end at corner (scaffolding level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-9/15/2008	North Face - West end at corner (scaffolding level)	9/15/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-9/16/2008	Southwest Area (sidewalk bridge level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST2-9/16/2008	Southeast Area (sidewalk bridge level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST5-9/16/2008	Firehouse #10 (roof level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-9/16/2008	North Side Sidewalk Bridge	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST100-9/16/2008	Station 10 Field Duplicate	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST11-9/16/2008	90 Trinity Place (roof level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST12-9/16/2008	110 Greenwich Street (roof level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-9/16/2008	Marriott Hotel, 38th Floor (roof level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST14-9/16/2008	West Face - South end at corner (scaffolding level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-9/16/2008	South Face - East end at corner (scaffolding level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST16-9/16/2008	East Face - North end at corner (scaffolding level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-9/16/2008	North Face - West end at corner (scaffolding level)	9/16/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	

Note:

1. The PM 10 reading at Station 4 (Northwest Area [street-level]) on September 16, 2008 was not available on account of instrument malfunction.