TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-9/18/2009	Southwest Area (sidewalk bridge level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-9/18/2009	Southeast Area (sidewalk bridge level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST4-9/18/2009	Northwest Area (street-level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST5-9/18/2009	Firehouse #10 (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST10-9/18/2009	North Side Sidewalk Bridge	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST100-9/18/2009	Station 10 Field Duplicate	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-9/18/2009	90 Trinity Place (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST13-9/18/2009	Marriott Hotel, 38th Floor (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST1-9/19/2009	Southwest Area (sidewalk bridge level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-9/19/2009	Southeast Area (sidewalk bridge level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST4-9/19/2009	Northwest Area (street-level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST5-9/19/2009	Firehouse #10 (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-9/19/2009	North Side Sidewalk Bridge	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-9/19/2009	Station 10 Field Duplicate	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST11-9/19/2009	90 Trinity Place (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST13-9/19/2009	Marriott Hotel, 38th Floor (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST1-9/20/2009	Southwest Area (sidewalk bridge level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST2-9/20/2009	Southeast Area (sidewalk bridge level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST4-9/20/2009	Northwest Area (street-level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST5-9/20/2009	Firehouse #10 (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST10-9/20/2009	North Side Sidewalk Bridge	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST100-9/20/2009	Station 10 Field Duplicate	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST11-9/20/2009	90 Trinity Place (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST12-9/20/2009	110 Greenwich Street (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-9/20/2009	Marriott Hotel, 38th Floor (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

Note:

^{1.} The PM10 readings from Station 12 (110 Greenwich Street [roof level]) on September 18 and 19, 2009 were not available on account of instrument malfunction.