TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	1
PM10-ST1-9/24/2007	Southwest Area (sidewalk bridge level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-9/24/2007	Southeast Area (sidewalk bridge level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST4-9/24/2007	Northwest Area (street-level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST5-9/24/2007	Firehouse #10 (roof level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST10-9/24/2007	North Side Sidewalk Bridge	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-9/25/2007	Station 10 Field Duplicate	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST12-9/24/2007	110 Greenwich Street (roof level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST13-9/24/2007	Marriott Hotel, 38th Floor (roof level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST14-9/24/2007	West Face - South end at corner (scaffolding level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST15-9/24/2007	South Face - East end at corner (scaffolding level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-9/24/2007	East Face - North end at corner (scaffolding level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-9/24/2007	North Face - West end at corner (scaffolding level)	9/24/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-9/25/2007	Southwest Area (sidewalk bridge level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST2-9/25/2007	Southeast Area (sidewalk bridge level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST4-9/25/2007	Northwest Area (street-level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST5-9/25/2007	Firehouse #10 (roof level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST10-9/25/2007	North Side Sidewalk Bridge	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST11-9/25/2007	90 Trinity Place (roof level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM10-ST12-9/25/2007	110 Greenwich Street (roof level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-9/25/2007	Marriott Hotel, 38th Floor (roof level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM10-ST14-9/25/2007	West Face - South end at corner (scaffolding level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST15-9/25/2007	South Face - East end at corner (scaffolding level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST16-9/25/2007	East Face - North end at corner (scaffolding level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST17-9/25/2007	North Face - West end at corner (scaffolding level)	9/25/07	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	

- The PM 10 reading at Station 11 (90 Trinity Place [roof level]) on September 24, 2007 was not available on account of instrument malfunction.
 The PM 10 reading at Station 100 (Station 10 Field Duplicate) on September 25, 2007 was not available on account of instrument malfunction.