

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-9/29/2008	Southwest Area (sidewalk bridge level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST2-9/29/2008	Southeast Area (sidewalk bridge level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST4-9/29/2008	Northwest Area (street-level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-9/29/2008	Firehouse #10 (roof level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST10-9/29/2008	North Side Sidewalk Bridge	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-9/29/2008	Station 10 Field Duplicate	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST11-9/29/2008	90 Trinity Place (roof level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-9/29/2008	110 Greenwich Street (roof level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST13-9/29/2008	Marriott Hotel, 38th Floor (roof level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST14-9/29/2008	West Face - South end at corner (scaffolding level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-9/29/2008	South Face - East end at corner (scaffolding level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST17-9/29/2008	North Face - West end at corner (scaffolding level)	9/29/08	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST1-9/30/2008	Southwest Area (sidewalk bridge level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST2-9/30/2008	Southeast Area (sidewalk bridge level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST4-9/30/2008	Northwest Area (street-level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST5-9/30/2008	Firehouse #10 (roof level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST10-9/30/2008	North Side Sidewalk Bridge	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST100-9/30/2008	Station 10 Field Duplicate	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST11-9/30/2008	90 Trinity Place (roof level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST12-9/30/2008	110 Greenwich Street (roof level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST13-9/30/2008	Marriott Hotel, 38th Floor (roof level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-9/30/2008	West Face - South end at corner (scaffolding level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST15-9/30/2008	South Face - East end at corner (scaffolding level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST17-9/30/2008	North Face - West end at corner (scaffolding level)	9/30/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	

Note:  
1. The PM10 readings at Station 16 (East Face - North end at corner [scaffolding level]) on Spetember 29 and 30, 2008 were not available on account of instrument malfunction.