

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-10/15/2008	Southwest Area (sidewalk bridge level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST2-10/15/2008	Southeast Area (sidewalk bridge level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST4-10/15/2008	Northwest Area (street-level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST5-10/15/2008	Firehouse #10 (roof level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM10-ST100-10/15/2008	Station 10 Field Duplicate	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST11-10/15/2008	90 Trinity Place (roof level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM10-ST12-10/15/2008	110 Greenwich Street (roof level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM10-ST13-10/15/2008	Marriott Hotel, 38th Floor (roof level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST14-10/15/2008	West Face - South end at corner (scaffolding level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST15-10/15/2008	South Face - East end at corner (scaffolding level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-10/15/2008	East Face - North end at corner (scaffolding level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST17-10/15/2008	North Face - West end at corner (scaffolding level)	10/15/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST1-10/16/2008	Southwest Area (sidewalk bridge level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	42	No	No	
PM10-ST2-10/16/2008	Southeast Area (sidewalk bridge level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST4-10/16/2008	Northwest Area (street-level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	34	No	No	
PM10-ST5-10/16/2008	Firehouse #10 (roof level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	43	No	No	
PM10-ST10-10/16/2008	North Side Sidewalk Bridge	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST100-10/16/2008	Station 10 Field Duplicate	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	47	No	No	
PM10-ST11-10/16/2008	90 Trinity Place (roof level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	57	No	No	
PM10-ST12-10/16/2008	110 Greenwich Street (roof level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST13-10/16/2008	Marriott Hotel, 38th Floor (roof level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	
PM10-ST14-10/16/2008	West Face - South end at corner (scaffolding level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST15-10/16/2008	South Face - East end at corner (scaffolding level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM10-ST16-10/16/2008	East Face - North end at corner (scaffolding level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST17-10/16/2008	North Face - West end at corner (scaffolding level)	10/16/08	1440	Particulate	Direct Read	Met One E-BAM	24	No	No	

Note:

1. The PM10 reading at Station 10 (North Side Sidewalk Bridge) on October 15, 2008 was not available on account of instrument malfunction.