

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-10/27/2005	Southwest Area (street-level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM10-ST2-10/27/2005	Southeast Area (sidewalk bridge level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST4-10/27/2005	Northwest Area (street-level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST5-10/27/2005	Firehouse #10 (roof level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST10-10/27/2005	North Side Sidewalk Bridge	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST100-10/27/2005	Station 10 Field Duplicate	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM10-ST11-10/27/2005	90 Trinity Place (roof level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM10-ST12-10/27/2005	110 Greenwich Street (roof level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM10-ST13-10/27/2005	Marriott Hotel, 38th Floor (roof level)	10/27/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM10-ST1-10/28/2005	Southwest Area (street-level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM10-ST2-10/28/2005	Southeast Area (sidewalk bridge level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST4-10/28/2005	Northwest Area (street-level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	13.0	No	No	
PM10-ST5-10/28/2005	Firehouse #10 (roof level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	13.0	No	No	
PM10-ST10-10/28/2005	North Side Sidewalk Bridge	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST100-10/28/2005	Station 10 Field Duplicate	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM10-ST11-10/28/2005	90 Trinity Place (roof level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST12-10/28/2005	110 Greenwich Street (roof level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST13-10/28/2005	Marriott Hotel, 38th Floor (roof level)	10/28/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST1-10/29/2005	Southwest Area (street-level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST2-10/29/2005	Southeast Area (sidewalk bridge level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST4-10/29/2005	Northwest Area (street-level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST5-10/29/2005	Firehouse #10 (roof level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST10-10/29/2005	North Side Sidewalk Bridge	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST100-10/29/2005	Station 10 Field Duplicate	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM10-ST11-10/29/2005	90 Trinity Place (roof level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	13.0	No	No	
PM10-ST12-10/29/2005	110 Greenwich Street (roof level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM10-ST13-10/29/2005	Marriott Hotel, 38th Floor (roof level)	10/29/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	