

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>150</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>150</b>			
PM10-ST1-11/3/2005	Southwest Area (street-level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST2-11/3/2005	Southeast Area (sidewalk bridge level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	40.3	No	No	
PM10-ST4-11/3/2005	Northwest Area (street-level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST5-11/3/2005	Firehouse #10 (roof level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST10-11/3/2005	North Side Sidewalk Bridge	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST11-11/3/2005	90 Trinity Place (roof level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM10-ST12-11/3/2005	110 Greenwich Street (roof level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM10-ST13-11/3/2005	Marriott Hotel, 38th Floor (roof level)	11/3/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST1-11/4/2005	Southwest Area (street-level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	40.3	No	No	
PM10-ST2-11/4/2005	Southeast Area (sidewalk bridge level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	55.9	No	No	
PM10-ST4-11/4/2005	Northwest Area (street-level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	39.0	No	No	
PM10-ST5-11/4/2005	Firehouse #10 (roof level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST10-11/4/2005	North Side Sidewalk Bridge	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	No	No	
PM10-ST11-11/4/2005	90 Trinity Place (roof level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST12-11/4/2005	110 Greenwich Street (roof level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST13-11/4/2005	Marriott Hotel, 38th Floor (roof level)	11/4/2005	1440	Particulate	Direct Read	Met One E-BAM	52.0	No	No	
PM10-ST1-11/5/2005	Southwest Area (street-level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST2-11/5/2005	Southeast Area (sidewalk bridge level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	70.2	No	No	
PM10-ST4-11/5/2005	Northwest Area (street-level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	53.3	No	No	
PM10-ST5-11/5/2005	Firehouse #10 (roof level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	61.1	No	No	
PM10-ST10-11/5/2005	North Side Sidewalk Bridge	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	68.9	No	No	
PM10-ST11-11/5/2005	90 Trinity Place (roof level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	49.4	No	No	
PM10-ST12-11/5/2005	110 Greenwich Street (roof level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	50.7	No	No	
PM10-ST13-11/5/2005	Marriott Hotel, 38th Floor (roof level)	11/5/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	