TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							150	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							150	Levels	Trigger Levels	
PM10-ST1-11/20/2006	Southwest Area (sidewalk bridge level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST2-11/20/2006	Southeast Area (sidewalk bridge level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST4-11/20/2006	Northwest Area (street-level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST5-11/20/2006	Firehouse #10 (roof level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-11/20/2006	North Side Sidewalk Bridge	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST100-11/20/2006	Station 10 Field Duplicate	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST11-11/20/2006	90 Trinity Place (roof level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST12-11/20/2006	110 Greenwich Street (roof level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST13-11/20/2006	Marriott Hotel, 38th Floor (roof level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST14-11/20/2006	West Face - South end at corner (scaffolding level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM10-ST15-11/20/2006	South Face - East end at corner (scaffolding level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST16-11/20/2006	East Face - North end at corner (scaffolding level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM10-ST17-11/20/2006	North Face - West end at corner (scaffolding level)	11/20/06	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM10-ST1-11/21/2006	Southwest Area (sidewalk bridge level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST2-11/21/2006	Southeast Area (sidewalk bridge level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST4-11/21/2006	Northwest Area (street-level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST5-11/21/2006	Firehouse #10 (roof level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST10-11/21/2006	North Side Sidewalk Bridge	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST100-11/21/2006	Station 10 Field Duplicate	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-11/21/2006	90 Trinity Place (roof level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST13-11/21/2006	Marriott Hotel, 38th Floor (roof level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST14-11/21/2006	West Face - South end at corner (scaffolding level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM10-ST15-11/21/2006	South Face - East end at corner (scaffolding level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST16-11/21/2006	East Face - North end at corner (scaffolding level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-11/21/2006	North Face - West end at corner (scaffolding level)	11/21/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	

Note:
1. PM 10 reading at Station 12 (110 Greenwich Street [roof level]) on November 21, 2006 was not available on account of instrument malfunction.