

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							150			
							150			
PM10-ST1-12/7/2006	Southwest Area (sidewalk bridge level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST2-12/7/2006	Southeast Area (sidewalk bridge level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST4-12/7/2006	Northwest Area (street-level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST5-12/7/2006	Firehouse #10 (roof level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST10-12/7/2006	North Side Sidewalk Bridge	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST100-12/7/2006	Station 10 Field Duplicate	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST11-12/7/2006	90 Trinity Place (roof level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST12-12/7/2006	110 Greenwich Street (roof level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST13-12/7/2006	Marriott Hotel, 38th Floor (roof level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST14-12/7/2006	West Face - South end at corner (scaffolding level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-12/7/2006	South Face - East end at corner (scaffolding level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-12/7/2006	East Face - North end at corner (scaffolding level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-12/7/2006	North Face - West end at corner (scaffolding level)	12/7/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST1-12/8/2006	Southwest Area (sidewalk bridge level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST2-12/8/2006	Southeast Area (sidewalk bridge level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST4-12/8/2006	Northwest Area (street-level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST5-12/8/2006	Firehouse #10 (roof level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	54	No	No	
PM10-ST10-12/8/2006	North Side Sidewalk Bridge	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-12/8/2006	Station 10 Field Duplicate	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST11-12/8/2006	90 Trinity Place (roof level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-12/8/2006	110 Greenwich Street (roof level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST13-12/8/2006	Marriott Hotel, 38th Floor (roof level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST14-12/8/2006	West Face - South end at corner (scaffolding level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM10-ST15-12/8/2006	South Face - East end at corner (scaffolding level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST16-12/8/2006	East Face - North end at corner (scaffolding level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM10-ST17-12/8/2006	North Face - West end at corner (scaffolding level)	12/8/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST1-12/9/2006	Southwest Area (sidewalk bridge level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST2-12/9/2006	Southeast Area (sidewalk bridge level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST4-12/9/2006	Northwest Area (street-level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST10-12/9/2006	North Side Sidewalk Bridge	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST100-12/9/2006	Station 10 Field Duplicate	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST11-12/9/2006	90 Trinity Place (roof level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST12-12/9/2006	110 Greenwich Street (roof level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST13-12/9/2006	Marriott Hotel, 38th Floor (roof level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST14-12/9/2006	West Face - South end at corner (scaffolding level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST15-12/9/2006	South Face - East end at corner (scaffolding level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST16-12/9/2006	East Face - North end at corner (scaffolding level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-12/9/2006	North Face - West end at corner (scaffolding level)	12/9/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST1-12/10/2006	Southwest Area (sidewalk bridge level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST2-12/10/2006	Southeast Area (sidewalk bridge level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST4-12/10/2006	Northwest Area (street-level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST10-12/10/2006	North Side Sidewalk Bridge	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST100-12/10/2006	Station 10 Field Duplicate	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST11-12/10/2006	90 Trinity Place (roof level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST12-12/10/2006	110 Greenwich Street (roof level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST13-12/10/2006	Marriott Hotel, 38th Floor (roof level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST14-12/10/2006	West Face - South end at corner (scaffolding level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST15-12/10/2006	South Face - East end at corner (scaffolding level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-12/10/2006	East Face - North end at corner (scaffolding level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM10-ST17-12/10/2006	North Face - West end at corner (scaffolding level)	12/10/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST1-12/11/2006	Southwest Area (sidewalk bridge level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST2-12/11/2006	Southeast Area (sidewalk bridge level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST4-12/11/2006	Northwest Area (street-level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST5-12/11/2006	Firehouse #10 (roof level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM10-ST10-12/11/2006	North Side Sidewalk Bridge	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM10-ST100-12/11/2006	Station 10 Field Duplicate	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST11-12/11/2006	90 Trinity Place (roof level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST12-12/11/2006	110 Greenwich Street (roof level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST13-12/11/2006	Marriott Hotel, 38th Floor (roof level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM10-ST14-12/11/2006	West Face - South end at corner (scaffolding level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM10-ST15-12/11/2006	South Face - East end at corner (scaffolding level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST16-12/11/2006	East Face - North end at corner (scaffolding level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST17-12/11/2006	North Face - West end at corner (scaffolding level)	12/11/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	

Note:

1. The PM 10 readings at Station 5 (Firehouse #10 [roof level]) on December 9 and 10, 2006 were not available for analysis on account of pump failure.