TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							40	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							65	Levels	Trigger Levels	
PM2.5-ST1-3/24/2008	Southwest Area (sidewalk bridge level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST2-3/24/2008	Southeast Area (sidewalk bridge level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST4-3/24/2008	Northwest Area (street-level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST5-3/24/2008	Firehouse #10 (roof level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST10-3/24/2008	North Side Sidewalk Bridge	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST100-3/24/2008	Station 10 Field Duplicate	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-3/24/2008	90 Trinity Place (roof level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST12-3/24/2008	110 Greenwich Street (roof level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-3/24/2008	Marriott Hotel, 38th Floor (roof level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-3/24/2008	South Face - East end at corner (scaffolding level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST16-3/24/2008	East Face - North end at corner (scaffolding level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST17-3/24/2008	North Face - West end at corner (scaffolding level)	3/24/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST1-3/25/2008	Southwest Area (sidewalk bridge level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST2-3/25/2008	Southeast Area (sidewalk bridge level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST4-3/25/2008	Northwest Area (street-level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST5-3/25/2008	Firehouse #10 (roof level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST10-3/25/2008	North Side Sidewalk Bridge	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST100-3/25/2008	Station 10 Field Duplicate	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST11-3/25/2008	90 Trinity Place (roof level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST12-3/25/2008	110 Greenwich Street (roof level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-3/25/2008	Marriott Hotel, 38th Floor (roof level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-3/25/2008	South Face - East end at corner (scaffolding level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST16-3/25/2008	East Face - North end at corner (scaffolding level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST17-3/25/2008	North Face - West end at corner (scaffolding level)	3/25/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	

Note:

1. The PM 2.5 readings at Station 14 (West Face - South end at corner [scaffolding level]) on March 24 and 25, 2008 were not available on account of instrument malfunction.