

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-3/31/2008	Southwest Area (sidewalk bridge level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-3/31/2008	Southeast Area (sidewalk bridge level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST4-3/31/2008	Northwest Area (street-level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST5-3/31/2008	Firehouse #10 (roof level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST10-3/31/2008	North Side Sidewalk Bridge	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST100-3/31/2008	Station 10 Field Duplicate	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST11-3/31/2008	90 Trinity Place (roof level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST12-3/31/2008	110 Greenwich Street (roof level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-3/31/2008	Marriott Hotel, 38th Floor (roof level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST14-3/31/2008	West Face - South end at corner (scaffolding level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-3/31/2008	South Face - East end at corner (scaffolding level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-3/31/2008	East Face - North end at corner (scaffolding level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST17-3/31/2008	North Face - West end at corner (scaffolding level)	3/31/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST1-4/1/2008	Southwest Area (sidewalk bridge level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST2-4/1/2008	Southeast Area (sidewalk bridge level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM2.5-ST4-4/1/2008	Northwest Area (street-level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST5-4/1/2008	Firehouse #10 (roof level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	33	No	No	
PM2.5-ST10-4/1/2008	North Side Sidewalk Bridge	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-4/1/2008	Station 10 Field Duplicate	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST11-4/1/2008	90 Trinity Place (roof level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST12-4/1/2008	110 Greenwich Street (roof level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-4/1/2008	Marriott Hotel, 38th Floor (roof level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST15-4/1/2008	South Face - East end at corner (scaffolding level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-4/1/2008	East Face - North end at corner (scaffolding level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST17-4/1/2008	North Face - West end at corner (scaffolding level)	4/1/08	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	

Note:

1. The PM 2.5 reading at Station 14 (West Face - South end at corner [scaffolding level]) on April 1, 2008 was not available on account of instrument malfunction.