

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-5/15/2006	Southwest Area (sidewalk bridge level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-5/15/2006	Southeast Area (sidewalk bridge level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST4-5/15/2006	Northwest Area (street-level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST5-5/15/2006	Firehouse #10 (roof level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST10-5/15/2006	North Side Sidewalk Bridge	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST100-5/15/2006	Station 10 Field Duplicate	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-5/15/2006	90 Trinity Place (roof level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST12-5/15/2006	110 Greenwich Street (roof level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST13-5/15/2006	Marriott Hotel, 38th Floor (roof level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST14-5/15/2006	West Face - South end at corner (scaffolding level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST15-5/15/2006	South Face - East end at corner (scaffolding level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	30	No	No	
PM2.5-ST16-5/15/2006	East Face - North end at corner (scaffolding level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST17-5/15/2006	North Face - West end at corner (scaffolding level)	5/15/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST1-5/16/2006	Southwest Area (sidewalk bridge level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST2-5/16/2006	Southeast Area (sidewalk bridge level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM2.5-ST4-5/16/2006	Northwest Area (street-level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST5-5/16/2006	Firehouse #10 (roof level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-5/16/2006	North Side Sidewalk Bridge	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM2.5-ST100-5/16/2006	Station 10 Field Duplicate	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-5/16/2006	90 Trinity Place (roof level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST12-5/16/2006	110 Greenwich Street (roof level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST13-5/16/2006	Marriott Hotel, 38th Floor (roof level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST14-5/16/2006	West Face - South end at corner (scaffolding level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST15-5/16/2006	South Face - East end at corner (scaffolding level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST16-5/16/2006	East Face - North end at corner (scaffolding level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST17-5/16/2006	North Face - West end at corner (scaffolding level)	5/16/06	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	