

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>							<b>40</b>			
<b>EPA Site Specific Trigger Levels</b>							<b>65</b>			
PM2.5-ST1-6/19/2009	Southwest Area (sidewalk bridge level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST2-6/19/2009	Southeast Area (sidewalk bridge level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST4-6/19/2009	Northwest Area (street-level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST5-6/19/2009	Firehouse #10 (roof level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST10-6/19/2009	North Side Sidewalk Bridge	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-6/19/2009	Station 10 Field Duplicate	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST11-6/19/2009	90 Trinity Place (roof level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST12-6/19/2009	110 Greenwich Street (roof level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST13-6/19/2009	Marriott Hotel, 38th Floor (roof level)	6/19/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST1-6/20/2009	Southwest Area (sidewalk bridge level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-6/20/2009	Southeast Area (sidewalk bridge level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST4-6/20/2009	Northwest Area (street-level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST5-6/20/2009	Firehouse #10 (roof level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST10-6/20/2009	North Side Sidewalk Bridge	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST100-6/20/2009	Station 10 Field Duplicate	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST11-6/20/2009	90 Trinity Place (roof level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST12-6/20/2009	110 Greenwich Street (roof level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST13-6/20/2009	Marriott Hotel, 38th Floor (roof level)	6/20/09	1440	Particulate	Direct Read	Met One E-BAM	31	No	No	
PM2.5-ST1-6/21/2009	Southwest Area (sidewalk bridge level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST2-6/21/2009	Southeast Area (sidewalk bridge level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST4-6/21/2009	Northwest Area (street-level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST5-6/21/2009	Firehouse #10 (roof level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST10-6/21/2009	North Side Sidewalk Bridge	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST100-6/21/2009	Station 10 Field Duplicate	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST11-6/21/2009	90 Trinity Place (roof level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST12-6/21/2009	110 Greenwich Street (roof level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST13-6/21/2009	Marriott Hotel, 38th Floor (roof level)	6/21/09	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	