TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							40	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							65	Levels	Trigger Levels	1
PM2.5-ST1-8/13/2007	Southwest Area (sidewalk bridge level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST2-8/13/2007	Southeast Area (sidewalk bridge level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	22	No	No	
PM2.5-ST5-8/13/2007	Firehouse #10 (roof level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST10-8/13/2007	North Side Sidewalk Bridge	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM2.5-ST100-8/13/2007	Station 10 Field Duplicate	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST11-8/13/2007	90 Trinity Place (roof level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	28	No	No	
PM2.5-ST12-8/13/2007	110 Greenwich Street (roof level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	19	No	No	
PM2.5-ST13-8/13/2007	Marriott Hotel, 38th Floor (roof level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM2.5-ST14-8/13/2007	West Face - South end at corner (scaffolding level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST15-8/13/2007	South Face - East end at corner (scaffolding level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST16-8/13/2007	East Face - North end at corner (scaffolding level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST17-8/13/2007	North Face - West end at corner (scaffolding level)	8/13/07	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST1-8/14/2007	Southwest Area (sidewalk bridge level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-8/14/2007	Southeast Area (sidewalk bridge level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST4-8/14/2007	Northwest Area (street-level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST5-8/14/2007	Firehouse #10 (roof level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST10-8/14/2007	North Side Sidewalk Bridge	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST100-8/14/2007	Station 10 Field Duplicate	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST11-8/14/2007	90 Trinity Place (roof level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST12-8/14/2007	110 Greenwich Street (roof level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST13-8/14/2007	Marriott Hotel, 38th Floor (roof level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST14-8/14/2007	West Face - South end at corner (scaffolding level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST15-8/14/2007	South Face - East end at corner (scaffolding level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST16-8/14/2007	East Face - North end at corner (scaffolding level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST17-8/14/2007	North Face - West end at corner (scaffolding level)	8/14/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	

Note:
1. The PM 2.5 reading at Station 4 (Northwest Area [street-level]) on August 13, 2007 was not available on account of instrument malfunction.