

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments	
							40				
Target Air Quality Levels											
EPA Site Specific Trigger Levels							65				
PM2.5-ST1-9/12/2007	Southwest Area (sidewalk bridge level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No		
PM2.5-ST2-9/12/2007	Southeast Area (sidewalk bridge level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No		
PM2.5-ST4-9/12/2007	Northwest Area (street-level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No		
PM2.5-ST5-9/12/2007	Firehouse #10 (roof level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST10-9/12/2007	North Side Sidewalk Bridge	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No		
PM2.5-ST100-9/12/2007	Station 10 Field Duplicate	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	13	No	No		
PM2.5-ST12-9/12/2007	110 Greenwich Street (roof level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No		
PM2.5-ST13-9/12/2007	Marriott Hotel, 38th Floor (roof level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		
PM2.5-ST14-9/12/2007	West Face - South end at corner (scaffolding level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No		
PM2.5-ST15-9/12/2007	South Face - East end at corner (scaffolding level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST16-9/12/2007	East Face - North end at corner (scaffolding level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST17-9/12/2007	North Face - West end at corner (scaffolding level)	9/12/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		
PM2.5-ST1-9/13/2007	Southwest Area (sidewalk bridge level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST2-9/13/2007	Southeast Area (sidewalk bridge level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	14	No	No		
PM2.5-ST4-9/13/2007	Northwest Area (street-level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		
PM2.5-ST5-9/13/2007	Firehouse #10 (roof level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No		
PM2.5-ST10-9/13/2007	North Side Sidewalk Bridge	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST100-9/13/2007	Station 10 Field Duplicate	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No		
PM2.5-ST12-9/13/2007	110 Greenwich Street (roof level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST13-9/13/2007	Marriott Hotel, 38th Floor (roof level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		
PM2.5-ST14-9/13/2007	West Face - South end at corner (scaffolding level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No		
PM2.5-ST15-9/13/2007	South Face - East end at corner (scaffolding level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		
PM2.5-ST16-9/13/2007	East Face - North end at corner (scaffolding level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No		
PM2.5-ST17-9/13/2007	North Face - West end at corner (scaffolding level)	9/13/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No		

Note:

1. The PM 2.5 readings at Station 11 (90 Trinity Place [roof level]) on September 12 and 13, 2007 were not available on account of instrument malfunction.