

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							40			
EPA Site Specific Trigger Levels							65			
PM2.5-ST1-9/18/2009	Southwest Area (sidewalk bridge level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST2-9/18/2009	Southeast Area (sidewalk bridge level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST4-9/18/2009	Northwest Area (street-level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST5-9/18/2009	Firehouse #10 (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST10-9/18/2009	North Side Sidewalk Bridge	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST100-9/18/2009	Station 10 Field Duplicate	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST11-9/18/2009	90 Trinity Place (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST12-9/18/2009	110 Greenwich Street (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST13-9/18/2009	Marriott Hotel, 38th Floor (roof level)	9/18/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST1-9/19/2009	Southwest Area (sidewalk bridge level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST2-9/19/2009	Southeast Area (sidewalk bridge level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST4-9/19/2009	Northwest Area (street-level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST5-9/19/2009	Firehouse #10 (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST10-9/19/2009	North Side Sidewalk Bridge	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST100-9/19/2009	Station 10 Field Duplicate	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST11-9/19/2009	90 Trinity Place (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	4	No	No	
PM2.5-ST12-9/19/2009	110 Greenwich Street (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST13-9/19/2009	Marriott Hotel, 38th Floor (roof level)	9/19/09	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-9/20/2009	Southwest Area (sidewalk bridge level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST2-9/20/2009	Southeast Area (sidewalk bridge level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST4-9/20/2009	Northwest Area (street-level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST5-9/20/2009	Firehouse #10 (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST10-9/20/2009	North Side Sidewalk Bridge	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST100-9/20/2009	Station 10 Field Duplicate	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST11-9/20/2009	90 Trinity Place (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST12-9/20/2009	110 Greenwich Street (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-9/20/2009	Marriott Hotel, 38th Floor (roof level)	9/20/09	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	