

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Target Air Quality Levels		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40	65			
							EPA Site Specific Trigger Levels				
PM2.5-ST1-11/10/2005	Southwest Area (street-level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	17.3		No	No	
PM2.5-ST2-11/10/2005	Southeast Area (sidewalk bridge level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	18.4		No	No	
PM2.5-ST4-11/10/2005	Northwest Area (street-level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	13.8		No	No	
PM2.5-ST5-11/10/2005	Firehouse #10 (roof level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	13.8		No	No	
PM2.5-ST10-11/10/2005	North Side Sidewalk Bridge	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	12.7		No	No	
PM2.5-ST100-11/10/2005	Station 10 Field Duplicate	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4		No	No	
PM2.5-ST11-11/10/2005	90 Trinity Place (roof level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	11.5		No	No	
PM2.5-ST12-11/10/2005	110 Greenwich Street (roof level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	11.5		No	No	
PM2.5-ST13-11/10/2005	Marriott Hotel, 38th Floor (roof level)	11/10/2005	1440	Particulate	Direct Read	Met One E-BAM	11.5		No	No	
PM2.5-ST1-11/11/2005	Southwest Area (street-level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	11.5		No	No	
PM2.5-ST2-11/11/2005	Southeast Area (sidewalk bridge level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	13.8		No	No	
PM2.5-ST4-11/11/2005	Northwest Area (street-level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	5.8		No	No	
PM2.5-ST5-11/11/2005	Firehouse #10 (roof level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	6.9		No	No	
PM2.5-ST10-11/11/2005	North Side Sidewalk Bridge	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	5.8		No	No	
PM2.5-ST100-11/11/2005	Station 10 Field Duplicate	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	4.6		No	No	
PM2.5-ST11-11/11/2005	90 Trinity Place (roof level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	5.8		No	No	
PM2.5-ST12-11/11/2005	110 Greenwich Street (roof level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	6.9		No	No	
PM2.5-ST13-11/11/2005	Marriott Hotel, 38th Floor (roof level)	11/11/2005	1440	Particulate	Direct Read	Met One E-BAM	5.8		No	No	
PM2.5-ST1-11/12/2005	Southwest Area (street-level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	23.0		No	No	
PM2.5-ST2-11/12/2005	Southeast Area (sidewalk bridge level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	21.9		No	No	
PM2.5-ST4-11/12/2005	Northwest Area (street-level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	16.1		No	No	
PM2.5-ST5-11/12/2005	Firehouse #10 (roof level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	17.3		No	No	
PM2.5-ST10-11/12/2005	North Side Sidewalk Bridge	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	16.1		No	No	
PM2.5-ST100-11/12/2005	Station 10 Field Duplicate	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	16.1		No	No	
PM2.5-ST11-11/12/2005	90 Trinity Place (roof level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	15.0		No	No	
PM2.5-ST12-11/12/2005	110 Greenwich Street (roof level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	16.1		No	No	
PM2.5-ST13-11/12/2005	Marriott Hotel, 38th Floor (roof level)	11/12/2005	1440	Particulate	Direct Read	Met One E-BAM	15.0		No	No	

Note: A correction factor of 1.15 was applied to the reported data. TRC does not believe a correction factor should be applied to this data; however, this has been performed as directed by the EPA.