

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
							40			
							65			
PM2.5-ST2-11/13/2006	Southeast Area (sidewalk bridge level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST4-11/13/2006	Northwest Area (street-level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST5-11/13/2006	Firehouse #10 (roof level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST10-11/13/2006	North Side Sidewalk Bridge	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST100-11/13/2006	Station 10 Field Duplicate	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST11-11/13/2006	90 Trinity Place (roof level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	21	No	No	
PM2.5-ST12-11/13/2006	110 Greenwich Street (roof level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	23	No	No	
PM2.5-ST13-11/13/2006	Marriott Hotel, 38th Floor (roof level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST14-11/13/2006	West Face - South end at corner (scaffolding level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST15-11/13/2006	South Face - East end at corner (scaffolding level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST16-11/13/2006	East Face - North end at corner (scaffolding level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM2.5-ST17-11/13/2006	North Face - West end at corner (scaffolding level)	11/13/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST1-11/14/2006	Southwest Area (sidewalk bridge level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST2-11/14/2006	Southeast Area (sidewalk bridge level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST4-11/14/2006	Northwest Area (street-level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	14	No	No	
PM2.5-ST5-11/14/2006	Firehouse #10 (roof level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST10-11/14/2006	North Side Sidewalk Bridge	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST100-11/14/2006	Station 10 Field Duplicate	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST11-11/14/2006	90 Trinity Place (roof level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM2.5-ST12-11/14/2006	110 Greenwich Street (roof level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	17	No	No	
PM2.5-ST13-11/14/2006	Marriott Hotel, 38th Floor (roof level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST14-11/14/2006	West Face - South end at corner (scaffolding level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	
PM2.5-ST15-11/14/2006	South Face - East end at corner (scaffolding level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST16-11/14/2006	East Face - North end at corner (scaffolding level)	11/14/06	1440	Particulate	Direct Read	Met One E-BAM	12	No	No	

Note:

- PM 2.5 reading at Station 1 (Southwest Area [sidewalk bridge level]) on November 13, 2006 was not available on account of instrument malfunction.
- PM 2.5 reading at Station 17 (North Face - West end at corner [scaffolding level]) on November 14, 2006 was not available on account of instrument malfunction.