TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels							40	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels							65	Levels	Trigger Levels	
PM2.5-ST1-12/24/2007	Southwest Area (sidewalk bridge level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST2-12/24/2007	Southeast Area (sidewalk bridge level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST4-12/24/2007	Northwest Area (street-level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST5-12/24/2007	Firehouse #10 (roof level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST100-12/24/2007	Station 10 Field Duplicate	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST11-12/24/2007	90 Trinity Place (roof level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	5	No	No	
PM2.5-ST12-12/24/2007	110 Greenwich Street (roof level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST14-12/24/2007	West Face - South end at corner (scaffolding level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	7	No	No	
PM2.5-ST15-12/24/2007	South Face - East end at corner (scaffolding level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST16-12/24/2007	East Face - North end at corner (scaffolding level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST17-12/24/2007	North Face - West end at corner (scaffolding level)	12/24/07	1440	Particulate	Direct Read	Met One E-BAM	6	No	No	
PM2.5-ST1-12/25/2007	Southwest Area (sidewalk bridge level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	8	No	No	
PM2.5-ST2-12/25/2007	Southeast Area (sidewalk bridge level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST4-12/25/2007	Northwest Area (street-level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST5-12/25/2007	Firehouse #10 (roof level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST10-12/25/2007	North Side Sidewalk Bridge	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST100-12/25/2007	Station 10 Field Duplicate	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST11-12/25/2007	90 Trinity Place (roof level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST12-12/25/2007	110 Greenwich Street (roof level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST13-12/25/2007	Marriott Hotel, 38th Floor (roof level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	9	No	No	
PM2.5-ST14-12/25/2007	West Face - South end at corner (scaffolding level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST15-12/25/2007	South Face - East end at corner (scaffolding level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	
PM2.5-ST16-12/25/2007	East Face - North end at corner (scaffolding level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	10	No	No	
PM2.5-ST17-12/25/2007	North Face - West end at corner (scaffolding level)	12/25/07	1440	Particulate	Direct Read	Met One E-BAM	11	No	No	

Note: 1. The PM 2.5 readings at Station 10 (North Side Sidewalk Bridge) and Station 13 (Marriott Hotel, 38th Floor [roof level]) on December 24, 2007 were not available on account of instrument malfunction.