

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
										Target Air Quality Levels				
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-1/12/07	030701386-0001	Southwest Area (sidewalk bridge level)	1/12/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST2-1/12/07	030701386-0002	Southeast Area (sidewalk bridge level)	1/12/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST4-1/12/07	030701386-0003	Northwest Area (street-level)	1/12/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST5-1/12/07	030701386-0004	Firehouse #10 (roof level)	1/12/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST10-1/12/07	030701386-0005	North Side Sidewalk Bridge	1/12/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST11-1/12/07	030701386-0006	90 Trinity Place (roof level)	1/12/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST12-1/12/07	030701386-0007	110 Greenwich Street (roof level)	1/12/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST13-1/12/07	030701386-0008	Marriott Hotel, 38th Floor (roof level)	1/12/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST14-1/12/07	030701386-0009	West Face - South end at corner (scaffolding level)	1/12/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST15-1/12/07	030701386-0010	South Face - East end at corner (scaffolding level)	1/12/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST16-1/12/07	030701386-0011	East Face - North end at corner (scaffolding level)	1/12/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST17-1/12/07	030701386-0012	North Face - West end at corner (scaffolding level)	1/12/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST1-1/13/07	030701385-0001	Southwest Area (sidewalk bridge level)	1/13/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST2-1/13/07	030701385-0002	Southeast Area (sidewalk bridge level)	1/13/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST4-1/13/07	030701385-0003	Northwest Area (street-level)	1/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST5-1/13/07	030701385-0004	Firehouse #10 (roof level)	1/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST10-1/13/07	030701385-0005	North Side Sidewalk Bridge	1/13/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST11-1/13/07	030701385-0006	90 Trinity Place (roof level)	1/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST12-1/13/07	030701385-0007	110 Greenwich Street (roof level)	1/13/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST13-1/13/07	030701385-0008	Marriott Hotel, 38th Floor (roof level)	1/13/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST14-1/13/07	030701385-0009	West Face - South end at corner (scaffolding level)	1/13/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST15-1/13/07	030701385-0010	South Face - East end at corner (scaffolding level)	1/13/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST16-1/13/07	030701385-0011	East Face - North end at corner (scaffolding level)	1/13/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST17-1/13/07	030701385-0012	North Face - West end at corner (scaffolding level)	1/13/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST1-1/14/07	030701387-0001	Southwest Area (sidewalk bridge level)	1/14/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST2-1/14/07	030701387-0002	Southeast Area (sidewalk bridge level)	1/14/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST4-1/14/07	030701387-0003	Northwest Area (street-level)	1/14/07	1	3.400	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	Note 1
ASBESTOS-ST5-1/14/07	030701387-0004	Firehouse #10 (roof level)	1/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST10-1/14/07	030701387-0005	North Side Sidewalk Bridge	1/14/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST11-1/14/07	030701387-0006	90 Trinity Place (roof level)	1/14/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST12-1/14/07	030701387-0007	110 Greenwich Street (roof level)	1/14/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST13-1/14/07	030701387-0008	Marriott Hotel, 38th Floor (roof level)	1/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST14-1/14/07	030701387-0009	West Face - South end at corner (scaffolding level)	1/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST15-1/14/07	030701387-0010	South Face - East end at corner (scaffolding level)	1/14/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST16-1/14/07	030701387-0011	East Face - North end at corner (scaffolding level)	1/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 15.00		No	No	
ASBESTOS-ST17-1/14/07	030701387-0012	North Face - West end at corner (scaffolding level)	1/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/15/07	< 13.00		No	No	
ASBESTOS-ST1-1/15/07	030701503-0001	Southwest Area (sidewalk bridge level)	1/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST2-1/15/07	030701503-0002	Southeast Area (sidewalk bridge level)	1/15/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 15.00		No	No	
ASBESTOS-ST4-1/15/07	030701503-0003	Northwest Area (street-level)	1/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 15.00		No	No	
ASBESTOS-ST5-1/15/07	030701503-0004	Firehouse #10 (roof level)	1/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST10-1/15/07	030701503-0005	North Side Sidewalk Bridge	1/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST100-1/15/07	030701503-0013	Station 10 Field Duplicate	1/15/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 15.00		No	No	
ASBESTOS-ST11-1/15/07	030701503-0006	90 Trinity Place (roof level)	1/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST12-1/15/07	030701503-0007	110 Greenwich Street (roof level)	1/15/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST13-1/15/07	030701503-0008	Marriott Hotel, 38th Floor (roof level)	1/15/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 15.00		No	No	
ASBESTOS-ST14-1/15/07	030701503-0009	West Face - South end at corner (scaffolding level)	1/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST15-1/15/07	030701503-0010	South Face - East end at corner (scaffolding level)	1/15/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST16-1/15/07	030701503-0011	East Face - North end at corner (scaffolding level)	1/15/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	
ASBESTOS-ST17-1/15/07	030701503-0012	North Face - West end at corner (scaffolding level)	1/15/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/16/07	< 13.00		No	No	

Note:  
1. Due to flow rate RPD exceedance (22.2%) for asbestos at Station 4 (Northwest Area [street-level]) on January 14, 2007, the sample volume and subsequent sample result are estimated.