

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments | |
|----------------------------------|----------------|-----------------------------------------------------|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--------------------|------------------------------|----------|--|
| | | | | | | | | | | NA | Air Quality Levels | Site Specific Trigger Levels | | |
| | | | | | | | | | | 70 | | | | |
| Target Air Quality Levels | | | | | | | | | | | | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | | | | |
| ASBESTOS-ST1-1/17/08 | 030801534-0001 | Southwest Area (sidewalk bridge level) | 1/17/08 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST2-1/17/08 | 030801534-0002 | Southeast Area (sidewalk bridge level) | 1/17/08 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST4-1/17/08 | 030801534-0003 | Northwest Area (street-level) | 1/17/08 | 1 | 2.920 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST5-1/17/08 | 030801534-0004 | Firehouse #10 (roof level) | 1/17/08 | 1 | 2.890 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST10-1/17/08 | 030801534-0005 | North Side Sidewalk Bridge | 1/17/08 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST11-1/17/08 | 030801534-0006 | 90 Trinity Place (roof level) | 1/17/08 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST12-1/17/08 | 030801534-0007 | 110 Greenwich Street (roof level) | 1/17/08 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST13-1/17/08 | 030801534-0008 | Marriott Hotel, 38th Floor (roof level) | 1/17/08 | 1 | 3.180 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST14-1/17/08 | 030801534-0009 | West Face - South end at corner (scaffolding level) | 1/17/08 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST15-1/17/08 | 030801534-0010 | South Face - East end at corner (scaffolding level) | 1/17/08 | 1 | 2.870 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST16-1/17/08 | 030801534-0011 | East Face - North end at corner (scaffolding level) | 1/17/08 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |
| ASBESTOS-ST17-1/17/08 | 030801534-0012 | North Face - West end at corner (scaffolding level) | 1/17/08 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 1/18/08 | < 13.00 | No | No | | |