

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-1/31/06	030603136-0001	Southwest Area (sidewalk bridge level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST2-1/31/06	030603136-0002	Southeast Area (sidewalk bridge level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST4-1/31/06	030603136-0003	Northwest Area (street-level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST5-1/31/06	030603136-0004	Firehouse #10 (roof level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST10-1/31/06	030603136-0005	North Side Sidewalk Bridge	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST11-1/31/06	030603136-0006	90 Trinity Place (roof level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST12-1/31/06	030603136-0007	110 Greenwich Street (roof level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST13-1/31/06	030603136-0008	Marriott Hotel, 38th Floor (roof level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST14-1/31/06	030603136-0009	West Face - South end at corner (scaffolding level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST15-1/31/06	030603136-0010	South Face - East end at corner (scaffolding level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST16-1/31/06	030603136-0011	East Face - North end at corner (scaffolding level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST17-1/31/06	030603136-0012	North Face - West end at corner (scaffolding level)	1/31/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/1/06	< 13.00	No	No		
ASBESTOS-ST1-2/1/06	030603249-0001	Southwest Area (sidewalk bridge level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST2-2/1/06	030603249-0002	Southeast Area (sidewalk bridge level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST4-2/1/06	030603249-0003	Northwest Area (street-level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST5-2/1/06	030603249-0004	Firehouse #10 (roof level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST10-2/1/06	030603249-0005	North Side Sidewalk Bridge	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST100-2/1/06	030603249-0013	Station 10 Field Duplicate	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST11-2/1/06	030603249-0006	90 Trinity Place (roof level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST12-2/1/06	030603249-0007	110 Greenwich Street (roof level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST13-2/1/06	030603249-0008	Marriott Hotel, 38th Floor (roof level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST14-2/1/06	030603249-0009	West Face - South end at corner (scaffolding level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST15-2/1/06	030603249-0010	South Face - East end at corner (scaffolding level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST16-2/1/06	030603249-0011	East Face - North end at corner (scaffolding level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST17-2/1/06	030603249-0012	North Face - West end at corner (scaffolding level)	2/1/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/2/06	< 13.00	No	No		
ASBESTOS-ST1-2/2/06	030603424-0001	Southwest Area (sidewalk bridge level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST2-2/2/06	030603424-0002	Southeast Area (sidewalk bridge level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST4-2/2/06	030603424-0003	Northwest Area (street-level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST5-2/2/06	030603424-0004	Firehouse #10 (roof level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST10-2/2/06	030603424-0005	North Side Sidewalk Bridge	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST11-2/2/06	030603424-0006	90 Trinity Place (roof level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST12-2/2/06	030603424-0007	110 Greenwich Street (roof level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST13-2/2/06	030603424-0008	Marriott Hotel, 38th Floor (roof level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST14-2/2/06	030603424-0009	West Face - South end at corner (scaffolding level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST15-2/2/06	030603424-0010	South Face - East end at corner (scaffolding level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST16-2/2/06	030603424-0011	East Face - North end at corner (scaffolding level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		
ASBESTOS-ST17-2/2/06	030603424-0012	North Face - West end at corner (scaffolding level)	2/2/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/3/06	< 13.00	No	No		