

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-2/13/07	030704667-0001	Southwest Area (sidewalk bridge level)	2/13/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST2-2/13/07	030704667-0002	Southeast Area (sidewalk bridge level)	2/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST4-2/13/07	030704667-0003	Northwest Area (street-level)	2/13/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST5-2/13/07	030704667-0004	Firehouse #10 (roof level)	2/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST10-2/13/07	030704667-0005	North Side Sidewalk Bridge	2/13/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST11-2/13/07	030704667-0006	90 Trinity Place (roof level)	2/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST12-2/13/07	030704667-0007	110 Greenwich Street (roof level)	2/13/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST13-2/13/07	030704667-0008	Marriott Hotel, 38th Floor (roof level)	2/13/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/07	< 13.00	No	No	
ASBESTOS-ST1-2/14/07	030704745-0001	Southwest Area (sidewalk bridge level)	2/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 15.00	No	No	
ASBESTOS-ST2-2/14/07	030704745-0002	Southeast Area (sidewalk bridge level)	2/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 13.00	No	No	
ASBESTOS-ST4-2/14/07	030704745-0003	Northwest Area (street-level)	2/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 15.00	No	No	
ASBESTOS-ST5-2/14/07	030704745-0004	Firehouse #10 (roof level)	2/14/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 13.00	No	No	
ASBESTOS-ST10-2/14/07	030704745-0005	North Side Sidewalk Bridge	2/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 13.00	No	No	
ASBESTOS-ST11-2/14/07	030704745-0006	90 Trinity Place (roof level)	2/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 15.00	No	No	
ASBESTOS-ST12-2/14/07	030704745-0007	110 Greenwich Street (roof level)	2/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 15.00	No	No	
ASBESTOS-ST13-2/14/07	030704745-0008	Marriott Hotel, 38th Floor (roof level)	2/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/15/07	< 15.00	No	No	

Note:

1. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on February 13 and 14, 2007 were not available for analysis. The stations were inaccessible on account of ice on the scaffolding.